

RECEIVED

# OIL AND GAS CONSERVATION COMMISSION DEPARTMENT OF NATURAL RESOURCES THE STATE OF COLORADO



00500088

duplicate for Patented and Federal lands.  
File in triplicate for State lands.

OCT 23 1985

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

OIL WELL ☐ GAS WELL ☐ OTHER ☐ P&A

NAME OF OPERATOR

Wintershall Petroleum Corporation

ADDRESS OF OPERATOR

5675 DTC Blvd., Ste. 200, Englewood, CO 80111

LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)

At surface 1800' FNL & 1350' FEL

At proposed prod. zone

Same

5. LEASE DESIGNATION AND SERIAL NO.

FEE

6. IF INDIAN, ALLOTTEE OR MINOR, NAME OF LEASE

None

7. UNIT AGREEMENT NAME

None

8. FARM OR LEASE NAME

Hull

9. WELL NO.

#28-32

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 28, T15S-R42W

12. COUNTY

Cheyenne

13. STATE

Colorado

1. PERMIT NO.

85-1248

15. ELEVATIONS (Show whether DF, WT, GR, etc.)

4005'GR; 4010'KB

### Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON

CHANGE PLANS

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

SUBSEQUENT REPORT OF:

REPAIRING WELL

ALTERING CASING

ABANDONMENT

7. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Date of work 10/19/85

Verbal permission was granted by Jim McKee, at 9 p.m., 10/18/85, to plug well as follows:

Plug #1 from top of Morrow down with 25 sxs.  
Plug #2 from top of Lansing down with 25 sxs.  
Plug #3 half in and half out across base of surface casing with 25 sxs.  
Plug #4 at surface with 10 sxs. Cut off 3' below ground and weld plate over surface pipe.

18. I hereby certify that the foregoing is true and correct

SIGNED

David R. Howell

TITLE

Operations Manager

DATE

10/22/85

(This space for Federal or State office use)

APPROVED BY

William Smith

TITLE

DIRECTOR

DATE

OCT 30 1985

CONDITIONS OF APPROVAL, IF ANY:

