

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402234177

Date Received:

11/07/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 39560

Name of Operator: TOP OPERATING COMPANY

Address: 3609 S WADSWORTH BLVD STE 340

City: LAKEWOOD State: CO Zip: 80235

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Paul Herring

720-663-1698

paul.herring@topoperating.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 699300424

Inspection Date: 10/23/2019

FIR Submit Date: 10/23/2019

FIR Status: _____

Inspected Operator Information:

Company Name: TOP OPERATING COMPANY

Company Number: 39560

Address: 3609 S WADSWORTH BLVD STE 340

City: LAKEWOOD State: CO Zip: 80235

LOCATION - Location ID: 317954

Location Name: COUNTER-62N66W Number: 30NENE County: WELD

Qtrqr: NENE Sec: 30 Twp: 2N Range: 66W Meridian: 6

Latitude: 40.114650 Longitude: -104.813030

FACILITY - API Number: 05-123- -00 Facility ID: 240247

Facility Name: COUNTER Number: 2

Qtrqr: NENE Sec: 30 Twp: 2N Range: 66W Meridian: 6

Latitude: 40.114650 Longitude: -104.813030

CORRECTIVE ACTIONS:

1 ☒ CA# 131938

Corrective Action: Comply with rule 603.f

Date: 12/18/2019

Response: CA COMPLETED

Date of Completion: 10/18/2019

Operator
Comment:

TOP submitted a FIRR doc id 402184324 on 9/20/2019 in which TOP asked for a "Factual Review" of the finding on the inspection report. TOP has a written agreement with the surface to store equipment at this location in compensation for building and maintaining the bridge at the location that provides access across the drainage ditch. This was submitted on a previous inspection (doc id = 401477140) in 2017 and accepted by another inspector.

Attached is the agreement with the surface owner. This agreement has been in place since 1974 and was commenced by the previous operator, Calvin Petroleum. TOP now operates this lease and as such inherited this

agreement, among other items.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 ☒ CA# 131939

Corrective Action: Conduct maintenance on equipment, cleanup stained material and review self inspection processes. Comply with Rule 1002..(2).D

Date: 10/18/2019

Response: CA COMPLETED

Date of Completion: 10/18/2019

Operator
Comment:

The leak on the horizontal separator has been repaired and stained soil has been removed.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Paul Herring

Signed: _____

Title: Landman

Date: 11/7/2019 4:47:57 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402234177	FIR RESOLUTION SUBMITTED
402234237	Original letter from surface owner
402234239	Separator housing

Total Attach: 3 Files