

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402195396

Date Received:  
10/02/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10133  
Name of Operator: HILCORP ENERGY COMPANY  
Address: P O BOX 61229  
City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Ray, Mandy</u>	<u>(505) 599-4083</u>	<u>mray@hilcorp.com</u>
<u>Shorty, Priscilla</u>		<u>pshorty@hilcorp.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693900740  
Inspection Date: 08/29/2019 FIR Submit Date: 09/09/2019 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY Company Number: 10133  
Address: P O BOX 61229  
City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 326452

Location Name: ARGENTA 33-10-N33N10W Number: 3SENW County: LA PLATA  
Qtrqtr: SENW Sec: 3 Twp: 33N Range: 10W Meridian: N  
Latitude: 37.136090 Longitude: -107.923900

FACILITY - API Number: 05-067-00 Facility ID: 216522

Facility Name: ARGENTA 33-10 Number: 3-1  
Qtrqtr: SENW Sec: 3 Twp: 33N Range: 10W Meridian: N  
Latitude: 37.136090 Longitude: -107.923900

CORRECTIVE ACTIONS:

1  CA# 130246

Corrective Action: Comply with rule 603f Date: 09/23/2019

Response: CA COMPLETED Date of Completion: 10/01/2019

Operator Comment: Weeds removed. See attached photos.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

2  CA# 130247

Corrective Action: Stormwater erosion needs to be controlled within the project area. Stormwater controls need to be selected, sized, installed, and maintained using good engineering practices such as those described in CDOT manuals for erosion control. Vegetation needs to be established within eroding areas. Access road needs to be repaired and stabilized.

Date: 09/27/2019

Response: CA COMPLETED

Date of Completion: 10/01/2019

Operator Comment: Access road and stormwater erosion repaired. See attached photos

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: PRISCILLA SHORTY

Signed: \_\_\_\_\_

Title: OperationsRegulatory Tech

Date: 10/2/2019 7:30:47 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402195396	FIR RESOLUTION SUBMITTED
402195413	Resolved Photos

Total Attach: 2 Files