

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402201024

Date Received:

10/07/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 6720

Name of Operator: ROBERT L BAYLESS PRODUCER LLC

Address: 621 17TH ST STE 2300

City: DENVER State: CO Zip: 80293

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Charles, Karen

kcharles@vefinc.com

Wells, Raymond

rwells@vefinc.com

Trujillo, Helen

505-564-7801

htrujillo@rlbayless.com

Sloan, Buddy

903-581-4382

rsloan@vefinc.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693900741

Inspection Date: 08/29/2019

FIR Submit Date: 09/09/2019

FIR Status: _____

Inspected Operator Information:

Company Name: FAULCONER INC* VERNON E

Company Number: 29200

Address: P O BOX 7995

City: TYLER State: TX Zip: 75711

LOCATION - Location ID: 325387

Location Name: INDIAN SPRINGS-N33N10W Number: 3SWNE County: LA PLATA

Qtrqr: SWNE Sec: 3 Twp: 33N Range: 10W Meridian: N

Latitude: 37.135580 Longitude: -107.918310

FACILITY - API Number: 05-067- -00 Facility ID: 214685

Facility Name: INDIAN SPRINGS Number: 2

Qtrqr: SWNE Sec: 3 Twp: 33N Range: 10W Meridian: N

Latitude: 37.135580 Longitude: -107.918310

CORRECTIVE ACTIONS:

1 ☒ CA# 130248

Corrective Action: Controls weeds. Flowering heads need to be removed, bagged, and properly disposed. Thistle rosettes need to be controlled. Subsequent treatment will likely be needed. Additional seeding/revegetation will be required if vegetation is damaged by weed treatment activities.

Date: 09/20/2019

Response: CA COMPLETED

Date of Completion: 10/04/2019

Operator Comment: WEEDS REMOVED, THEN SPRAYED FOR ANNUAL WEED SPRAYING

COGCC Decision: Approved pending re-inspection

COGCC Representative:

2 ☒ CA# 130249

Corrective Action: Stormwater erosion needs to be controlled within the project area. Stormwater controls need to be selected, sized, installed, and maintained using good engineering practices such as those described in CDOT manuals for erosion control. Access road needs to be repaired and stabilized.

Date: 09/27/2019

Response: CA COMPLETED

Date of Completion: 10/04/2019

Operator Comment: EROSION FIXED ON PAD AND ROAD

COGCC Decision: Approved pending re-inspection

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: WELL ACQUIRED BY ROBERT L. BAYLESS, PRODUCER LLC - AWAITING COGCC CHANGE OF OP. PLEASE CONTACT BAYLESS WITH ANY QUESTIONS. PLEASE SEE ATTACHED PHOTOS.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: HELEN TRUJILLO

Signed: _____

Title: PROD & REG ANALYST

Date: 10/7/2019 8:56:31 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402201024	FIR RESOLUTION SUBMITTED
402201037	PHOTOS

Total Attach: 2 Files