

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402217115

Date Received:

10/22/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Ray, Mandy</u>	<u>(505) 599-4083</u>	<u>mray@hilcorp.com</u>
<u>Shorty, Priscilla</u>		<u>pshorty@hilcorp.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693900820

Inspection Date: 09/16/2019

FIR Submit Date: 09/26/2019

FIR Status: _____

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY Company Number: 10133
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 325746

Location Name: HENRY-N32N7W Number: 2SENE County: LA PLATA
Qtrqr: SENE Sec: 2 Twp: 32N Range: 7W Meridian: N
Latitude: 37.048820 Longitude: -107.573370

FACILITY - API Number: 05-067- -00 Facility ID: 215328

Facility Name: HENRY Number: 2-2
Qtrqr: SENE Sec: 2 Twp: 32N Range: 7W Meridian: N
Latitude: 37.048820 Longitude: -107.573370

CORRECTIVE ACTIONS:

1 ☒ CA# 131154

Corrective Action: Control weeds

Date: 10/04/2019

Response: CA COMPLETED

Date of Completion: 10/17/2019

Operator Comment: Weeds were removed. Location was disked and seeded to help with erosion.
Erosional channeling was stabilized in southern portion by armoring drainage with sandstone.
Drainage was diverted around location.
See attached photos

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 ☒ CA# 131155

Corrective Action: Stormwater controls need to be installed ot stabilize erosion within the southern project area.

Date: 10/10/2019

Response: CA COMPLETED

Date of Completion: 10/17/2019

Operator Comment: Weeds were removed. Location was disked and seeded to help with erosion.
Erosional channeling was stabilized in southern portion by armoring drainage with sandstone.
Drainage was diverted around location.
See attached photos

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: PRISCILLA SHORTY

Signed: _____

Title: OperationsRegulatory Tech

Date: 10/22/2019 10:43:22 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402217115	FIR RESOLUTION SUBMITTED
402217118	Henry 2-2 Resolved Photos

Total Attach: 2 Files