

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402276508

Date Received:  
01/02/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10464  
Name of Operator: CATAMOUNT ENERGY PARTNERS LLC  
Address: 1801 BROADWAY #1000  
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Recipient, Single</u>		<u>Inspections@catamountep.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693900297  
Inspection Date: 05/09/2019 FIR Submit Date: 05/15/2019 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: CATAMOUNT ENERGY PARTNERS LLC Company Number: 10464  
Address: 1801 BROADWAY #1000  
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 333415

Location Name: IGS Number: 156 County: LA PLATA  
Qtrqr: NWN Sec: 26 Twp: 33N Range: 9W Meridian: N  
W  
Latitude: 37.078970 Longitude: -107.801080

FACILITY - API Number: 05-067-00 Facility ID: 256491

Facility Name: DAVIS FR Number: 1  
Qtrqr: NWN Sec: 26 Twp: 33N Range: 9W Meridian: N  
W  
Latitude: 37.078970 Longitude: -107.801080

CORRECTIVE ACTIIONS:

1  CA# 125164

Corrective Action: Control weeds. Date: 06/30/2019

Response: CA COMPLETED Date of Completion: 06/12/2019

Operator Comment: Spray Russian knapweed.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

2  CA# 125165

Corrective Action: Remove waste and debris.

Date: 06/14/2019

Response: CA COMPLETED

Date of Completion: 05/30/2019

Operator  
Comment: Removed debris

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

3  CA# 125166

Corrective Action: Reclaim/revegetate disturbed soils within the western project area. Soil stabilization measures such as mulch (on flat areas) and erosion control blanket (on slopes) will likely be needed until soil is stabilized with perennial vegetation.

Date: 06/01/2019

Response: CA COMPLETED

Date of Completion: 05/30/2019

Operator  
Comment: Reseeded area and installed erosion control measures

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

4  CA# 125167

Corrective Action: Stormwater controls are needed to stabilize erosion near the well pad entrance, along the access road. Stormwater controls need to be installed using good engineering practices such as those described in CDOT stormwater erosion control guides.  
Additionally, as described above, erosion controls such as mulch and erosion control blankets are needed to stabilize exposed soils in the western project area, and along the western fill slope.

Date: 06/17/2019

Response: CA COMPLETED

Date of Completion: 05/30/2019

Operator  
Comment: Installed additional diversion channel and rock check dams along access road

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Nolan Redmond

Signed: \_\_\_\_\_

Title: Geo/Eng Tech

Date: 1/2/2020 4:14:27 PM

## ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402276508	FIR RESOLUTION SUBMITTED
402276523	Remedial Report

Total Attach: 2 Files