

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402342717

Date Received:  
03/13/2020

FIR RESOLUTION FORM

Overall Status: FRQ

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

0 CA Completed  
1 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672  
Name of Operator: TIMBER CREEK OPERATING LLC  
Address: 6295 GREENWOOD PLAZA BLVD #100  
City: GREENWOOD VILLAGE State: CO Zip: 8111-4978  
Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Mack, Ronald</u>	<u>719-859-4896</u>	<u>ronaldmack@tcenergyllc.com</u>
<u>Fitzgerald, Edie</u>	<u>719-859-1394</u>	<u>ediefitzgerald@tcenergyllc.com</u>
<u>BAKER DAVID</u>		<u>dbaker@auroramp.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 689901887  
Inspection Date: 03/12/2020 FIR Submit Date: 03/13/2020 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC Company Number: 10672  
Address: 6295 GREENWOOD PLAZA BLVD #100  
City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

LOCATION - Location ID: 309256

Location Name: HILL RANCH-634S67W Number: 25SESE County: LAS ANIMAS  
Qtrqr: SESE Sec: 25 Twp: 34S Range: 67W Meridian: 6  
Latitude: 37.049823 Longitude: -104.831770

FACILITY - API Number: 05-071-00 Facility ID: 290789

Facility Name: HILL RANCH Number: 25-16  
Qtrqr: SESE Sec: 25 Twp: 34S Range: 67W Meridian: 6  
Latitude: 37.049823 Longitude: -104.831770

CORRECTIVE ACTIONS:

1 CA# 137187

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C Date: 03/20/2020

Response: FACTUAL REVIEW REQUEST

Basis for Review: Equipment is not owned or controlled by the operator

Evergreen Natural Resources LLC owns the lease where the erosion is occurring. Timber Creek Energy LLC

Operator Comment: owns the lease west of the cattle guard at Lat. 37.04988 Long. -104.827597. That cattle guard is on the main road to Hill Ranch past the Evergreen access road to API # 05-071-09122 well name: Lorensito 14-30-34-66. There were no erosion issues found west of the cattle guard where Timber Creek's lease begins. See attached map for details.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

#### OPERATOR COMMENT AND SUBMITTAL

Comment: Timber Creek does not own the lease where the erosion has occurred.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed: \_\_\_\_\_

Title: SR. Environmental Tech.

Date: 3/13/2020 2:43:01 PM

### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402342818	Lease boundary map
-----------	--------------------

Total Attach: 1 Files