

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402342717

Date Received:
03/13/2020

FIR RESOLUTION FORM

Overall Status: FRQ

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

0 CA Completed
1 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672

Name of Operator: TIMBER CREEK OPERATING LLC

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Mack, Ronald

719-859-4896

ronaldmack@tcenergyllc.com

Fitzgerald, Edie

719-859-1394

ediefitzgerald@tcenergyllc.com

BAKER DAVID

dbaker@auroramp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 689901887

Inspection Date: 03/12/2020

FIR Submit Date: 03/13/2020

FIR Status: _____

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC

Company Number: 10672

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

LOCATION - Location ID: 309256

Location Name: HILL RANCH-634S67W Number: 25SESE County: LAS ANIMAS

Qtrqr: SESE Sec: 25 Twp: 34S Range: 67W Meridian: 6

Latitude: 37.049823 Longitude: -104.831770

FACILITY - API Number: 05-071- -00 Facility ID: 290789

Facility Name: HILL RANCH Number: 25-16

Qtrqr: SESE Sec: 25 Twp: 34S Range: 67W Meridian: 6

Latitude: 37.049823 Longitude: -104.831770

CORRECTIVE ACTIONS:

1 ☒ CA# 137187

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 03/20/2020

Response: FACTUAL REVIEW REQUEST

Basis for Review: Equipment is not owned or controlled by the operator

Evergreen Natural Resources LLC owns the lease where the erosion is occurring. Timber Creek Energy LLC owns the lease west of the cattle guard at Lat. 37.04988 Long. -104.827597. That cattle guard is on the main

Operator Comment: road to Hill Ranch past the Evergreen access road to API # 05-071-09122 well name: Lorensito 14-30-34-66. There were no erosion issues found west of the cattle guard where Timber Creek's lease begins. See attached map for details.

COGCC Decision: **Not Approved**

COGCC Representative: The same inspection was sent to the other operator that utilizes the lease road. Both operators are responsible for compliance of the corrective action and will need to coordinate to resolve the corrective action. This Factual Review is Not Approved.

COGCC Supervisor: The same inspection was sent to the other operator that utilizes the lease road. Both operators are responsible for compliance of the corrective action and will need to coordinate to resolve the corrective action. This Factual Review is Not Approved.

OPERATOR COMMENT AND SUBMITTAL

Comment: Timber Creek does not own the lease where the erosion has occurred.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed: _____

Title: SR. Environmental Tech.

Date: 3/13/2020 2:43:01 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402342717	FIR RESOLUTION SUBMITTED
402342818	Lease boundary map

Total Attach: 2 Files