

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402347570

Date Received:
03/19/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 1199 MAIN AVENUE SUITE 101
City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Beebe, Sabre</u>		<u>sabre.beebe@bpx.com</u>
<u>Arthur, Denise</u>		<u>denise.arthur@state.co.us</u>
<u>Gillette, Kira</u>		<u>kira.gillette@state.co.us</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693900989
Inspection Date: 10/22/2019 FIR Submit Date: 10/28/2019 FIR Status: _____

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000
Address: 1199 MAIN AVENUE SUITE 101
City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 325595

Location Name: BONDS GAS UNIT-N32N10W Number: 1SWSE County: LA PLATA
Qtrqtr: SWSE Sec: 1 Twp: 32N Range: 10W Meridian: N
Latitude: 37.041568 Longitude: -107.882923

FACILITY - API Number: 05-067-00 Facility ID: 215062

Facility Name: BONDS Number: 3E
Qtrqtr: SWSE Sec: 1 Twp: 32N Range: 10W Meridian: N
Latitude: 37.041568 Longitude: -107.882923

CORRECTIVE ACTIONS:

1 CA# 132064

Corrective Action: _____ Date: _____

Remove equipment and reclaim project area, including but not limited to, recontouring, decompaction, and revegetation. Weeds need to be controlled.

Operator is directed to perform corrective actions immediately. Doing so may decrease the duration of the alleged violations and the penalties that may be assessed pursuant to Rule 523.

Response: CA COMPLETED

Date of Completion: 03/12/2020

Operator Comment: Red Cedar Gathering removed their remaining equipment and riser from location. Land owner moved their equipment for ag production from the location. Stormwater, weeds and seeding addressed. variance being addressed through enforcement process.

COGCC Decision: _____

COGCC Representative: _____

2 CA# 132065

Corrective Action: Stabilize erosion within the project area. Reclamation and revegetation of the well pad will help stabilization. Stormwater and erosion controls will be needed until location meets final revegetation standards.

Date: _____

Operator is directed to perform corrective actions immediately. Doing so may decrease the duration of the alleged violations and the penalties that may be assessed pursuant to Rule 523.

Response: CA COMPLETED

Date of Completion: 03/12/2020

Operator Comment: Bare and disturbed areas were seeded after Red Cedar and Landowner removed their items from the location. Biodegradable coconut matting put into place for stabilization and keeping seed in place for germination. Stormwater pond with armored outlet installed.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: CA work done. Landowner variance being reworked through enforcement group.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: _____

Title: Specialist

Date: 3/19/2020 3:26:43 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402347583	Work photos
-----------	-------------

Total Attach: 1 Files