

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402281005

Date Received:
01/10/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10464

Name of Operator: CATAMOUNT ENERGY PARTNERS LLC

Address: 1801 BROADWAY #1000

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Recipient, Single

Inspections@catamountep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693900929

Inspection Date: 10/08/2019

FIR Submit Date: 10/17/2019

FIR Status: _____

Inspected Operator Information:

Company Name: CATAMOUNT ENERGY PARTNERS LLC

Company Number: 10464

Address: 1801 BROADWAY #1000

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 320861

Location Name: PARGIN MOUNTAIN UNIT-M34N5W Number: 34NESE County: ARCHULETA

Qtrqr: NESE Sec: 34 Twp: 34N Range: 5W Meridian: M

Latitude: 37.145360 Longitude: -107.373940

FACILITY - API Number: 05-007- -00 Facility ID: 205259

Facility Name: PARGIN MOUNTAIN UNIT Number: 9

Qtrqr: NESE Sec: 34 Twp: 34N Range: 5W Meridian: M

Latitude: 37.145360 Longitude: -107.373940

CORRECTIVE ACTIONS:

1 ☒ CA# 131763

Corrective Action: Cleanup stained material and review self inspection processes.

Date: 10/23/2019

Response: CA COMPLETED

Date of Completion: 10/09/2019

Operator
Comment: Cleaned up stained material.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 ☒ CA# 131764

Corrective Action: Remove and properly store unused equipment.

Date: 10/31/2019

Response: CA COMPLETED

Date of Completion: 12/12/2019

Operator
Comment: All Equipment Removed

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

3 ☒ CA# 131765

Corrective Action: Portions of the reclamation area with damaged vegetation need to be decompacted and re-seeded.

Date: 10/31/2019

Response: CA COMPLETED

Date of Completion: 12/12/2019

Operator
Comment: Reclaimed slopes.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

4 ☒ CA# 131766

Corrective Action: Stormwater (BMPs) and erosion controls (seeding and mulching) are needed to stabilize erosion on the well pad cut-slopes.

Date: 10/31/2019

Response: CA COMPLETED

Date of Completion: 12/12/2019

Operator
Comment: Reclaimed slopes

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Nolan Redmond

Signed:

Title: Geo/Eng Tech

Date: 1/10/2020 4:12:39 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402281005	FIR RESOLUTION SUBMITTED
402282834	Remedial Report

Total Attach: 2 Files