

APACHE CANYON 29-06 API# 05-071-09288 – TIMBER CREEK OPERATING  
OGCC OPERATOR NUMBER 10672 - DATE: MARCH 27, 2020  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 689901857



**PHOTO 1:** FACING SOUTHWEST ALONG THE MAIN LEASE ROAD IN LITTLE BINGHAM CANYON. ONCE THE SOIL DRIED OUT, THE MAIN LEASE ROAD SURFACE WAS CROWNED TO REMOVE THE TIRE RUTS AND ESTABLISH SHEET FLOW.

APACHE CANYON 29-06 API# 05-071-09288 – TIMBER CREEK OPERATING  
OGCC OPERATOR NUMBER 10672 - DATE: MARCH 27, 2020  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 689901857



**PHOTO 2:** FACING SOUTH ALONG THE MAIN LEASE ROAD IN LITTLE BINGHAM CANYON. THE MAIN LEASE ROAD SURFACE WAS CROWNED TO REMOVE THE TIRE RUTS AND ESTABLISH SHEET FLOW.

APACHE CANYON 29-06 API# 05-071-09288 – TIMBER CREEK OPERATING  
OGCC OPERATOR NUMBER 10672 - DATE: MARCH 27, 2020  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 689901857



**PHOTO 3:** FACING SOUTHWEST ALONG THE MAIN LEASE ROAD IN LITTLE BINGHAM CANYON. THE MAIN LEASE ROAD SURFACE WAS CROWNED TO REMOVE THE TIRE RUTS AND ESTABLISH SHEET FLOW.

APACHE CANYON 29-06 API# 05-071-09288 – TIMBER CREEK OPERATING  
OGCC OPERATOR NUMBER 10672 - DATE: MARCH 27, 2020  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 689901857



**PHOTO 4:** FACING SOUTHWEST ALONG THE MAIN LEASE ROAD. THE MAIN LEASE ROAD SURFACE WAS CROWNED TO REMOVE THE TIRE RUTS AND ESTABLISH SHEET FLOW.