

Scott Kerr

From: Scott Kerr
Sent: Monday, December 28, 2015 10:57 AM
To: rob.young@state.co.us
Cc: 'susan.sherman@state.co.us'; Tom Kirkwood; Dave Weinert
Subject: Rudnik Inspection 43B-27 Doc # 673712115
Attachments: 20151217232302152.pdf

Rob-

We received an inspection report from Susan Sherman-Colorado Oil and Gas that referenced a Rudnik Inspection 43B-27 Doc # 673712115 that contained action required items. She has referred us to you to resolve the environmental portion of the inspection. The inspection refers to a spill that occurred in 2013? and Wesco attempted to bio-remediate the material in-place. The quarterly monitoring reports were sent in to the Colorado Oil and Gas but apparently never arrived to the proper person and not uploaded into the State system. After a conversation with Axelson, it was clear the bio-remediation was not working and Wesco excavated the material, sampled and then backfilled the area (all within an active tank battery). See the attached correspondence and lab report.

If you could please take a look and see what it's going to take to close out the inspection. If you have any questions, please give me a call.

Thanks

Scott Kerr
HSE Coordinator
Wesco Operating, Inc.
120 South Durbin Street
P. O. Box 1650
Casper, Wyoming 82602
Office: (307) 577-5336
Cell: (307) 462-3844
Fax: (307) 265-1791
e-mail - scottk@kirkwoodcompanies.com