

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402353523

Date Received:  
03/26/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10133  
Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Shorty, Priscilla

pshorty@hilcorp.com

Ray, Mandy

(505) 599-4083

mray@hilcorp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693901253

Inspection Date: 12/20/2019

FIR Submit Date: 12/23/2019

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY

Company Number: 10133

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 326226

Location Name: HUBER-LEWIS-N34N8W Number: 4NWSE County: LA PLATA

Qtrqr: NWSE Sec: 4 Twp: 34N Range: 8W Meridian: N

Latitude: 37.241040 Longitude: -107.746630

FACILITY - API Number: 05-067- -00 Facility ID: 216068

Facility Name: HUBER-LEWIS Number: 2-4

Qtrqr: NWSE Sec: 4 Twp: 34N Range: 8W Meridian: N

Latitude: 37.241040 Longitude: -107.746630

CORRECTIVE ACTIONS:

1 ☒ CA# 135535

Corrective Action: Remove and properly dispose of weed debris.

Date: 01/23/2020

Response: CA COMPLETED

Date of Completion: 01/09/2020

Operator  
Comment: Weeds removed

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

2 ☒ CA# 135536

Corrective Action: Revegetation needs to be conducted within bare/weedy portion of the interim reclamation area where it appears that desirable vegetation was recently killed. Soil testing/soil amendments are recommended to ensure successful germination. As described below, erosion controls such as mulching need to be installed at the time of seeding to stabilize eroding soils.

Date: 04/01/2020

Response: CA COMPLETED

Date of Completion: 03/26/2020

Operator  
Comment: The southern rec site has been seeded.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

3 ☒ CA# 135537

Corrective Action: Stormwater controls (ie BMPs) need to be installed by 1/10/2020, to prevent sediment discharge from the project area. Stormwater controls need to be selected, sized, installed, and maintained according to good engineering practices. Additionally, erosion controls such as mulching or erosion blankets need to be installed by 4/1/2020 to stabilize bare soils until stabilized with desirable perennial vegetation.

Date: 01/10/2020

Response: CA COMPLETED

Date of Completion: 01/09/2020

Operator  
Comment: BMP'd installed

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Amanda Walker

Signed: \_\_\_\_\_

Title: Operation/Regulatory Tech

Date: 3/26/2020 3:13:29 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402353523	FIR RESOLUTION SUBMITTED
402353583	Weed Removed
402353584	BMP
402353587	BMP
402353597	Weed Removal
402353612	BMP

402353618	BMP
402353623	BMP

Total Attach: 8 Files