

Document Number:
402362953

Date Received:

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set. A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 16700 Contact Name: KEVIN HEJL

Name of Operator: CHEVRON USA INC Phone: (970) 250-9554

Address: 100 CHEVRON ROAD Fax: _____

City: RANGELY State: CO Zip: 81648 Email: KEVINHEJL@CHEVRON.COM

For "Intent" 24 hour notice required, Name: Moran, Rick Tel: (720) 827-6689

COGCC contact: Email: rick.moran@state.co.us

Type of Well Abandonment Report: Notice of Intent to Abandon Subsequent Report of Abandonment

API Number 05-103-07024-00

Well Name: F V LARSON B Well Number: 16-X

Location: QtrQtr: SESE Section: 26 Township: 2N Range: 102W Meridian: 6

County: RIO BLANCO Federal, Indian or State Lease Number: 47443

Field Name: RANGELY Field Number: 72370

Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.110390 Longitude: -108.805620

GPS Data: GPS Quality Value: 2.2 Type of GPS Quality Value: _____ Date of Measurement: 01/08/2007

GPS Instrument Operator's Name: John Floyd

Reason for Abandonment: Dry Production Sub-economic Mechanical Problems

Other _____

Casing to be pulled: Yes No Estimated Depth: _____

Fish in Hole: Yes No If yes, explain details below

Wellbore has Uncemented Casing leaks: Yes No If yes, explain details below

Details: TUBING FISH LEFT IN HOLE UNABLE TO FISH ESP. TUBING WAS CUT ABOVE DRAIN & CIBP SET ABOVE CUT DEPTH.

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
WEBER	6019	6378			
Total: 1 zone(s)					

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	15	10+3/4	40.5	968	650	968	14	VISU
1ST	9	7	23	5,336		5,336	14	CBL
2ND	9	7	23	6,458	810	6,458	5,336	CBL

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 5685 with 29 sacks cmt on top. CIBP #2: Depth 1130 with 29 sacks cmt on top.
 CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
 CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set <u>29</u> sks cmt from <u>5685</u> ft. to <u>5535</u> ft.	Plug Type: <u>CASING</u>	Plug Tagged: <input checked="" type="checkbox"/>
Set <u>116</u> sks cmt from <u>1050</u> ft. to <u>0</u> ft.	Plug Type: <u>ANNULUS</u>	Plug Tagged: <input type="checkbox"/>
Set <u>90</u> sks cmt from <u>1050</u> ft. to <u>880</u> ft.	Plug Type: <u>CASING</u>	Plug Tagged: <input type="checkbox"/>
Set <u>29</u> sks cmt from <u>880</u> ft. to <u>730</u> ft.	Plug Type: <u>CASING</u>	Plug Tagged: <input type="checkbox"/>
Set _____ sks cmt from _____ ft. to _____ ft.	Plug Type: _____	Plug Tagged: <input type="checkbox"/>

Perforate and squeeze at 1150 ft. with 29 sacks. Leave at least 100 ft. in casing 1130 CICR Depth
 Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
 Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
(Cast Iron Cement Retainer Depth)

Set _____ sacks half in. half out surface casing from _____ ft. to _____ ft. Plug Tagged:
 Set 10 sacks at surface
 Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No
 Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. _____ inch casing Cut and Cap Date: _____
 of _____
 *Wireline Contractor: _____ *Cementing Contractor: _____
 Type of Cement and Additives Used: _____
 Flowline/Pipeline has been abandoned per Rule 1105 Yes No

Technical Detail/Comments:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: ANITA SANFORD
 Title: REGULATORY TECH.ASSISANT Date: _____ Email: ATLX@CHEVRON.COM

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____ Date: _____

CONDITIONS OF APPROVAL, IF ANY: _____ Expiration Date: _____

COA Type	Description

Attachment Check List

<u>Att Doc Num</u>	<u>Name</u>
402363023	PROPOSED PLUGGING PROCEDURE
402363026	WELLBORE DIAGRAM
402363030	WELLBORE DIAGRAM

Total Attach: 3 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)