

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/25/2020

Submitted Date:

04/07/2020

Document Number:

688800710

FIELD INSPECTION FORMLoc ID 385368 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 74500

Name of Operator: REYNOLDS* NOEL

Address: BOX 356

City: FLORA VISTA State: NM Zip: 87415

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

3 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Heil, John		john.heil@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	
Chollett, Shannon		shannon.chollett@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214135	WELL	PA	06/16/1984	DA	067-05448	TOUCHSTONE-WEBER HEIRS (OWP) 1	EI

General Comment:

On March 25, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Noel Reynolds Touchstone Weber Heirs #1. For the most recent field inspection report of this facility, please refer to document #693900263.

Location**Lease Road:**

Type	Access		
comment:	Location accessed off of gravel road.		
Corrective ActionL		Date:	

Overall Good: ☒**Emergency Contact Number:**

Comment:		Date:	
Corrective Action:			

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	214135	Type:	WELL	API Number:	067-05448	Status:	PA	Insp. Status:	EI

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>On March 25, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Noel Reynolds Touchstone Weber Heirs #1. For the most recent field inspection report of this facility, please refer to document #693900263.</p> <p>The well head is the only equipment remaining on this location.</p> <p>Cement can be seen through the nipple on top of the well head and in the valve on the production casing.</p> <p>During this inspection, the Bradenhead valve was closed.</p> <p>Wooden debris near the well head may be the remains of a cellar.</p>	hughesjo	04/07/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800711	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5116940