

Inspection Photos

API: 071-09288

Operator: TIMBER CREEK OPERATING

Inspection Date: 4/6/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09288 | Date: 4/6/2020

Inspection Photos



Photo 1. Facing southeast through Little Bingham Canyon. The culvert has filled in with sediment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09288 | Date: 4/6/2020

Inspection Photos



Photo 2. Facing west as the road begins to ascend the hill. The road has been graded since the previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09288 | Date: 4/6/2020

Inspection Photos



Photo 3. A culvert is filled in with sediment as the road ascends the hill toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09288 | Date: 4/6/2020

Inspection Photos



Photo 4. There is erosion occurring at the culvert outlet as the lease road ascends the hill toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09288 | Date: 4/6/2020

Inspection Photos



Photo 5. Facing southwest as the road switch backs. The road has been recently graded.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09288 | Date: 4/6/2020

Inspection Photos



Photo 6. Facing southwest along the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09288 | Date: 4/6/2020

Inspection Photos



Photo 7. Facing northwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09288 | Date: 4/6/2020