

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/06/2020

Submitted Date:

04/08/2020

Document Number:

690200131

**FIELD INSPECTION FORM**Loc ID 309244 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10672

Name of Operator: TIMBER CREEK OPERATING LLC

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD State: CO Zip: 8111-

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

2 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Dylan Thomsen		timothy.thomsen@state.co.us	
BAKER DAVID		dbaker@auroramp.com	
Mack, Ronald		ronaldmack@tcenergyllc.com	
Fitzgerald, Edie		ediefitzgerald@tcenergyllc.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290652	WELL	PR	02/01/2008	GW	071-09288	APACHE CANYON 29-06	RI

**General Comment:**

This is a follow up of the previous inspection #689901857.  
The corrective action of the previous inspection has been performed.  
Additional corrective action has been identified.  
See attached photos and additional details within this report.

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts	Fail			
Comment:		<p>The road has been graded since the previous inspection. The vehicle rutting along the road has been repaired. Previous corrective action was performed.</p> <p>There are culverts along the main lease road that have filled in with sediment and need maintenance.</p>				
Corrective Action:		<p>Install or repair required BMPs per Rule 1002.f.(2)C</p>				Date: 05/08/2020
<b>Pits:</b> <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690200132	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5117942">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5117942</a>