

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402366009

Date Received:
04/08/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672

Name of Operator: TIMBER CREEK OPERATING LLC

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

BAKER DAVID

dbaker@auroramp.com

Dylan Thomsen

timothy.thomsen@state.co.us

Mack, Ronald

ronaldmack@tcenergyllc.com

Fitzgerald, Edie

ediefitzgerald@tcenergyllc.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 689901933

Inspection Date: 03/19/2020

FIR Submit Date: 03/20/2020

FIR Status: _____

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC

Company Number: 10672

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

LOCATION - Location ID: 309201

Location Name: NEW ELK-633S68W Number: 25SESE County: LAS ANIMAS

Qtrqtr: SESE Sec: 25 Twp: 33S Range: 68W Meridian: 6

Latitude: 37.137443 Longitude: -104.940352

FACILITY - API Number: 05-071- -00 Facility ID: 290088

Facility Name: NEW ELK Number: 25-16

Qtrqtr: SESE Sec: 25 Twp: 33S Range: 68W Meridian: 6

Latitude: 37.137443 Longitude: -104.940352

CORRECTIVE ACTIONS:

1 CA# 137343

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a.

Date: 03/27/2020

Response: CA COMPLETED

Date of Completion: 03/24/2020

The packing was replaced, and the packing nut was securely fastened to stop the leaking water at the well head.

Operator Comment: The soil below the well head was cleaned up. See the attached photo log for details.

COGCC Decision: _____

COGCC Representative: _____

2 CA# 137344

Corrective Action: Implement or modify BMPs for improved material handling and spill prevention. Immediately clean up area.

Date: 03/27/2020

Response: CA COMPLETED

Date of Completion: 03/24/2020

Operator Comment: The lid on the tank was closed and the side of the tank cleaned. See the attached photo log for details. The oily waste was removed from the PC engine skid and the liquid ring compressor skid immediately. The maintenance to the liquid ring compressor was completed on 04/03/20. The maintenance to the PC engine skid was completed on 04/06/20.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions have been addressed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed: _____

Title: SR. Environmental Tech.

Date: 4/8/2020 6:15:53 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402366014	Photo Log
-----------	-----------

Total Attach: 1 Files