



**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	x2		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Adequate	Date:	
Corrective Action:			

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	Panel x2		
Corrective Action:		Date:	

**Equipment:**

Type: Plunger Lift	# 2		corrective date
Comment:	The Lubricator plunger catcher on the Aloysius C34-32D is leaking.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date: 04/10/2020
Type: Bradenhead	# 2		
Comment:	Appear to be plumbed to surface.		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 239722 Type: WELL API Number: 123-07510 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

Facility ID: 415765 Type: WELL API Number: 123-31168 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<p><a href="#">COGCC Inspection Report Summary</a>                      On Thursday 4/9/20 at approximately 0808 hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Two E Ranches 1 &amp; Aloysius C34-32D of Noble Energy, at Location # 317659 in Weld County, Colorado.                      During this inspection the following possible compliance issues were observed:                      The Lubricator plunger catcher on the Aloysius C34-32D is leaking. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. With a corrective action date of 4/10/20.                      See attached photos.                      A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.                      Continuing education inspections</p>	burnsa	04/09/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699101455	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5119374">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5119374</a>