

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402307182

Date Received:  
02/10/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10464  
Name of Operator: CATAMOUNT ENERGY PARTNERS LLC  
Address: 1801 BROADWAY #1000  
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Recipient, Single</u>		<u>Inspections@catamountep.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693901104  
Inspection Date: 11/12/2019 FIR Submit Date: 11/20/2019 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: CATAMOUNT ENERGY PARTNERS LLC Company Number: 10464  
Address: 1801 BROADWAY #1000  
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 326237

Location Name: JAQUES-N33N8W Number: 27NWSE County: LA PLATA  
Qtrqr: NWSE Sec: 27 Twp: 33N Range: 8W Meridian: N  
Latitude: 37.071920 Longitude: -107.700180

FACILITY - API Number: 05-067-00 Facility ID: 216086

Facility Name: JAQUES Number: 6-F  
Qtrqr: NWSE Sec: 27 Twp: 33N Range: 8W Meridian: N  
Latitude: 37.071920 Longitude: -107.700180

CORRECTIVE ACTIONS:

1  CA# 134768

Corrective Action: Conduct revegetation throughout the interim reclamation areas. Weeds need to be controlled. Corrective action date is the date of this inspection as revegetation should be progressing at this time and needs to be conducted immediately.

Date: 11/12/2019

Response: CA COMPLETED Date of Completion: 02/06/2020

Operator Comment: Removed and disposed of weed debris, reseeded and applied straw mulch on bare cut slope, Will seed and mulch remaining slope when snow melts.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

2  CA# 134769

Corrective Action: Stormwater controls (ie BMPs) and erosion controls (ie mulching/blankets etc.) are needed to stabilize soils within the project area. Stormwater controls need to be selected, sized, installed, and maintained in accordance with good engineering practices such as those described by CDOT in their erosion control manuals.

Date: 11/29/2019

Response: CA COMPLETED

Date of Completion: 02/06/2020

Operator Comment: Installed drainage ditch at the top of the cut slope with rock catch basins at the outlets for storm water and erosion control. Installed straw mulch on bare slope.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Nolan Redmond

Signed: \_\_\_\_\_

Title: Geo/Eng Tech

Date: 2/10/2020 7:49:43 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402307182	FIR RESOLUTION SUBMITTED
402307186	Remedial Report

Total Attach: 2 Files