

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402369087

Date Received:
04/13/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672

Name of Operator: TIMBER CREEK OPERATING LLC

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

BAKER DAVID

dbaker@auroramp.com

Fitzgerald, Edie

ediefitzgerald@tcenergylc.com

Mack, Ronald

ronaldmack@tcenergylc.com

Dylan Thomsen

timothy.thomsen@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 689901935

Inspection Date: 03/19/2020

FIR Submit Date: 03/20/2020

FIR Status: _____

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC

Company Number: 10672

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

LOCATION - Location ID: 309202

Location Name: NEW ELK-633S68W Number: 36NENE County: LAS ANIMAS

Qtrqtr: NENE Sec: 36 Twp: 33S Range: 68W Meridian: 6

Latitude: 37.133887 Longitude: -104.940821

FACILITY - API Number: 05-071- -00 Facility ID: 290087

Facility Name: NEW ELK Number: 36-1

Qtrqtr: NENE Sec: 36 Twp: 33S Range: 68W Meridian: 6

Latitude: 37.133887 Longitude: -104.940821

CORRECTIVE ACTIONS:

1 CA# 137347

Corrective Action: Comply with Rule 603.f .

Date: 04/10/2020

Response: CA COMPLETED

Date of Completion: 04/10/2020

Operator Comment: All unused equipment was removed from the location. See attached photo log for details.

COGCC Decision: _____

COGCC Representative: _____

2 CA# 137348

Corrective Action: Repair and maintain lease road.

Date: 04/17/2020

Response: CA COMPLETED

Date of Completion: 04/10/2020

Operator Comment: The lease road was regraded to eliminate the tire ruts and establish sheet flow.

COGCC Decision: _____

COGCC Representative: _____

3 CA# 137349

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C
Implement or modify BMPs for improved material handling and spill prevention.
Immediately clean up area.

Date: 04/17/2020

Response: CA COMPLETED

Date of Completion: 04/10/2020

Operator Comment: The oily waste was removed from the PC engine skid and the liquid ring compressor skid immediately. The PC engine skid had a leak that was repaired on 04/09/20 and the skid was cleaned up on 04/10/20.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions have been addressed. See attached photo log for details.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed: _____

Title: SR. Environmental Tech.

Date: 4/13/2020 12:52:10 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402369103	Photo Log
-----------	-----------

Total Attach: 1 Files