

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402366009

Date Received:  
04/08/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672  
Name of Operator: TIMBER CREEK OPERATING LLC  
Address: 6295 GREENWOOD PLAZA BLVD #100  
City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>BAKER DAVID</u>		<u>dbaker@auroramp.com</u>
<u>Dylan Thomsen</u>		<u>timothy.thomsen@state.co.us</u>
<u>Mack, Ronald</u>		<u>ronaldmack@tcenergyllc.com</u>
<u>Fitzgerald, Edie</u>		<u>ediefitzgerald@tcenergyllc.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 689901933  
Inspection Date: 03/19/2020 FIR Submit Date: 03/20/2020 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC Company Number: 10672  
Address: 6295 GREENWOOD PLAZA BLVD #100  
City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

LOCATION - Location ID: 309201

Location Name: NEW ELK-633S68W Number: 25SESE County: LAS ANIMAS  
Qtrqr: SESE Sec: 25 Twp: 33S Range: 68W Meridian: 6  
Latitude: 37.137443 Longitude: -104.940352

FACILITY - API Number: 05-071-00 Facility ID: 290088

Facility Name: NEW ELK Number: 25-16  
Qtrqr: SESE Sec: 25 Twp: 33S Range: 68W Meridian: 6  
Latitude: 37.137443 Longitude: -104.940352

CORRECTIVE ACTIIONS:

1  CA# 137343

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Date: 03/27/2020

Response: CA COMPLETED Date of Completion: 03/24/2020

The packing was replaced, and the packing nut was securely fastened to stop the leaking water at the well head.

Operator Comment: The soil below the well head was cleaned up. See the attached photo log for details.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

2  CA# 137344

Corrective Action: Implement or modify BMPs for improved material handling and spill prevention. Immediately clean up area.

Date: 03/27/2020

Response: CA COMPLETED

Date of Completion: 03/24/2020

Operator Comment: The lid on the tank was closed and the side of the tank cleaned. See the attached photo log for details. The oily waste was removed from the PC engine skid and the liquid ring compressor skid immediately. The maintenance to the liquid ring compressor was completed on 04/03/20. The maintenance to the PC engine skid was completed on 04/06/20.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: All corrective actions have been addressed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald Signed: \_\_\_\_\_

Title: SR. Environmental Tech. Date: 4/8/2020 6:15:53 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402366009	FIR RESOLUTION SUBMITTED
402366014	Photo Log

Total Attach: 2 Files