

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402369107

Date Received:
04/13/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672

Name of Operator: TIMBER CREEK OPERATING LLC

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Dylan Thomsen

timothy.thomsen@state.co.us

Mack, Ronald

ronaldmack@tcenergyllc.com

BAKER DAVID

dbaker@auroramp.com

Fitzgerald, Edie

ediefitzgerald@tcenergyllc.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 689901937

Inspection Date: 03/19/2020

FIR Submit Date: 03/20/2020

FIR Status: _____

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC

Company Number: 10672

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

LOCATION - Location ID: 309200

Location Name: NEW ELK-633S68W Number: 36SWNW County: LAS ANIMAS

Qtrqr: SWN Sec: 36 Twp: 33S Range: 68W Meridian: 6
W

Latitude: 37.128453 Longitude: -104.952990

FACILITY - API Number: 05-071- -00 Facility ID: 290089

Facility Name: NEW ELK Number: 36-5

Qtrqr: SWN Sec: 36 Twp: 33S Range: 68W Meridian: 6
W

Latitude: 37.128453 Longitude: -104.952990

CORRECTIVE ACTIONS:

1 CA# 137350

Corrective Action: Repair and maintain lease road.

Date: 04/17/2020

Response: CA COMPLETED

Date of Completion: 04/10/2020

Operator
Comment:

The lease road was regraded to eliminate the erosion and establish sheet flow.

COGCC Decision: _____

COGCC
Representative:

2 CA# 137351

Corrective Action: Comply with Rule 603.f .

Date: 04/10/2020

Response: CA COMPLETED

Date of Completion: 04/10/2020

Operator
Comment:

All unused equipment was removed from the location. See attached photo log for details.

COGCC Decision: _____

COGCC
Representative:

3 CA# 137352

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C
Implement or modify BMPs for improved material handling and spill prevention.
Immediately clean up area.

Date: 04/17/2020

Response: CA COMPLETED

Date of Completion: 04/10/2020

Operator
Comment:

The sediment was removed from the culvert inlet. The lease road was regraded to eliminate the erosion and establish sheet flow. The impacted soil around the liquid ring was removed from location. The liquid ring compressor had a leak that was repaired, and the skid was cleaned up.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions have been addressed. See attached photo log for details.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed: _____

Title: SR. Environmental Tech.

Date: 4/13/2020 1:06:10 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402369124	Photo Log
-----------	-----------

Total Attach: 1 Files