

NEW ELK 36-05 API# 05-071-09236 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 10, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 689901937



PHOTO 1 AND 2: THE SEDIMENT ACCUMULATION WAS REMOVED FROM THE CULVERT INLET ALONG THE MAIN LEASE ROAD.

NEW ELK 36-05 API# 05-071-09236 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: MARCH 25, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 689901937



PHOTO 3: THE CLEAN UP OF THE IMPACTED SOIL NEXT TO THE LIQUID RING COMPRESSOR WAS COMPLETED ON MARCH 25.

NEW ELK 36-05 API# 05-071-09236 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 10, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 689901937



PHOTO 4: THE LEAKS FROM THE LIQUID RING COMPRESSOR WERE IDENTIFIED AND REPAIRED. THE LIQUID RING SKID WAS CLEANED UP ONCE THE REPAIRS WERE COMPLETED.

NEW ELK 36-05 API# 05-071-09236 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 10, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 689901937



PHOTO 5: THE UNUSED EQUIPMENT WAS REMOVED FROM LOCATION.

NEW ELK 36-05 API# 05-071-09236 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 10, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 689901937



PHOTO 6: THE UNUSED EQUIPMENT WAS REMOVED FROM LOCATION.

NEW ELK 36-05 API# 05-071-09236 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 10, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 689901937



PHOTO 7: THE MAIN LEASE ROAD WAS SURFACED CROWNED TO CREATE SHEET FLOW AND ELIMINATE THE SURFACE EROSION.