

TEP ROCKY MOUNTAIN LLC WILLIAMS-67S96W 1NWN Location # 334716



**TEP ROCKY MOUNTAIN LLC
WILLIAMS-67S96W 1NWNE
Location # 334716**



**Sediment build up in retention basin.
Lat/Long 39.472875 -108.05459**



Sediment build up in ditch

**TEP ROCKY MOUNTAIN LLC
WILLIAMS-67S96W 1NWNE
Location # 334716**



Washing of road at culvert.

Lat/Long 39.472689 -108.055189

Washing of road at culvert.

**TEP ROCKY MOUNTAIN LLC
WILLIAMS-67S96W 1NWNE
Location # 334716**



**Erosion of road shoulder across from plug well
location (UNOCAL GM 31-1 Api. # 05-045-07444)**



**Channeling of road shoulder/berm.
Lat/Long 39.472494 108.056294**

TEP ROCKY MOUNTAIN LLC
WILLIAMS-67S96W 1NWNE
Location # 334716



Channeling of road shoulder/berm.



Channeling of road shoulder/berm.

TEP ROCKY MOUNTAIN LLC
WILLIAMS-67S96W 1NWNE
Location # 334716



Channeling of road shoulder/berm.



Channeling of road shoulder/berm.

**TEP ROCKY MOUNTAIN LLC
WILLIAMS-67S96W 1NWNE
Location # 334716**



Erosion of road shoulder.

Lat/Long 39.472178 -108.056422

Erosion of road shoulder.

**TEP ROCKY MOUNTAIN LLC
WILLIAMS-67S96W 1NWNE
Location # 334716**



Erosion of road shoulder.

Lat/Long 39.472328 -108.57668