

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/09/2020

Submitted Date:

04/10/2020

Document Number:

700400944

FIELD INSPECTION FORMLoc ID 316192 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 200502

Name of Operator: 31 OPERATING

Address: 3021 RIDGE RD #156

City: ROCKWALL State: TX Zip: 75032

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor	970-415-0789	conor.pesicka@state.co.us	
Heil, John		john.heil@state.co.us	
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
Freeman, Kris	254-727-0435	kfreeman@31operating.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
256078	WELL	TA	04/01/2001	GW	103-09976	PARKER 4-35	TA

General Comment:

COGCC Inspection Report Summary.

On 4-9-2020 at approximately 15:00, inspector Rick Moran, conducted a follow up inspection at 31 Operating well Parker 4-35 in Rio Blanco county FIR documents:

- 1) 700400888 dated 4-6-2020.

The following compliance issues were resolved:

- 1) Unmarked deadman in NW corner.
- 2) Leak stopped.

The following compliance issues are uncompleted:

- 1) Sign has incorrect operator emergency phone number. Photo 3. Complete by 5-6-2020.
- 2) Lease road has culvert exposed. Photo 4. Complete by 5-6-2020.

A follow up inspection will occur to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 700400944.

LocationOverall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: The emergency phone number, 877-352-4660, on the well head sign is invalid.Corrective Action: Install sign to comply with Rule 210.b.

Date: 05/06/2020

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: Bull plug on well no longer leaking. Spill around well head was covered with a 1" to 2" deep layer of absorbent material. No apparent evidence of any soil removal.☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 256078 Type: WELL API Number: 103-09976 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: Last recorded production January 2002. Last MIT on 4-5-2017.

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts	Fail			

Comment: [Cuvert exposed on lease road.](#)Corrective Action: [Install or repair required BMPs per Rule 1002.f.](#)

Date: 05/06/2020

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402368039	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5120958
700400945	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5120957