

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/09/2020

Submitted Date:

04/20/2020

Document Number:

688800720

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
 \_\_\_\_\_ Hughes, Jim \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10000

Name of Operator: BP AMERICA PRODUCTION COMPANY

Address: 1199 MAIN AVENUE SUITE 101

City: DURANGO State: CO Zip: 81301

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☒ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

6 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Beebe, Sabre		sabre.beebe@bpx.com	<a href="#">All Inspections</a>
Heil, John		john.heil@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	
Inspections, All		SanJuanCOGCC@bp.com	<a href="#">SW Inspection Reports</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
474977	SPILL OR RELEASE	AC	04/14/2020		-	Tiffany Gathering	EI

**General Comment:**

On April 9, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Tiffany Gathering Line Spill/Release Point ID #474977. For more information regarding this release, please refer to document #402365707.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
Produced Water	Gathering Line	>= 5 bbls		
Comment: Gathering line failure in agricultural field.				
Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.			Date: 05/20/2020	

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type			
OTHER			
Comment: Temporary safety fencing installed to prevent access by livestock.			
Corrective Action:		Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 474977    Type: SPILL OR    API Number: -    Status: AC    Insp. Status: EI

**COGCC Comments**

Comment	User	Date
<p>On April 9, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Tiffany Gathering Line Spill/Release Point ID #474977. For more information regarding this release, please refer to document #402365707.</p> <p>Safety fencing has been installed to prevent access to the release area by livestock. An approximately 18 by 24" hole with fluid present was observed during this inspection. The area within the flow path is damp and has stained vegetation. The flow path terminates in an agricultural wetland. No evidence of flow on the downhill side of this area.</p> <p>The nearest surface water is uphill of the release point. This irrigation ditch was not flowing at the time of this inspection.</p>	hughesjo	04/20/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800721	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5127601">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5127601</a>