

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402360819

Date Received:

04/02/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000

Name of Operator: BP AMERICA PRODUCTION COMPANY

Address: 1199 MAIN AVENUE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Beebe, Sabre

SanJuanCOGCC@bp.com

Sabre.Beebe@bp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 680601354

Inspection Date: 03/24/2017

FIR Submit Date: 03/16/2017

FIR Status: _____

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY

Company Number: 10000

Address: 380 AIRPORT RD

City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 333471

Location Name: H N PEARSON A-M34N7W Number: 20SWNW County: LA PLATA

Qtrqr: SWN Sec: 20 Twp: 34N Range: 7W Meridian: M
W

Latitude: 37.179008 Longitude: -107.637704

FACILITY - API Number: 05-067- -00 Facility ID: 292371

Facility Name: HARRY PEARSON A Number: 3

Qtrqr: SWN Sec: 20 Twp: 34N Range: 7W Meridian: M
W

Latitude: 37.179008 Longitude: -107.637704

CORRECTIVE ACTIONS:

1 ☒ CA# 67002

Corrective Action: Remove junk and debris and equipment or provide a signed surface owner waiver (in accordance with recent guidance document "Rule 1001.c: Reclamation Waivers and Variances") accepting responsibility for materials stored on the well pad. This letter should define areas on the well pad where surface owner equipment will be stored.

Date: 05/19/2017

Response: CA COMPLETED

Date of Completion: 03/20/2020

Waste and debris cited in the inspection belonged to the landowner and legally BPX could not remove the debris

Operator Comment: and dispose of it without landowner authorization. Negotiations with the landowner and the reoccurring problem of encroachment has resulted in BPX having the landowner move their items and BPX installing fencing in an attempt to stop future encroachment. Debris has been moved by landowner and fencing installed see attached.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

2 ☒ CA# 67003

Corrective Action: Stormwater controls need to be installed to stabilize erosion within the northeastern portion of the project area.

Date: 04/21/2017

Response: CA COMPLETED

Date of Completion: 03/20/2020

Operator Comment: BP has addressed erosion CA by performing the following see attached photos:
Seeding
Erosion Repairs
Install Wattles
Install Rock Run Down
Repaired Berm
Grading of Well Pad
Removed sediment from BMP's

COGCC Decision: Approved pending re-inspection

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: All CA addressed

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: _____

Title: Specialist

Date: 4/2/2020 4:25:45 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402360819	FIR RESOLUTION SUBMITTED
402360824	Closure document

Total Attach: 2 Files