

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402363451

Date Received:
04/06/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 1199 MAIN AVENUE SUITE 101
City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Beebe, Sabre</u>		<u>sabre.beebe@bpx.com</u>
		<u>SanJuanCOGCC@bp.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693901083
Inspection Date: 11/06/2019 FIR Submit Date: 11/13/2019 FIR Status: _____

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000
Address: 1199 MAIN AVENUE SUITE 101
City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 325920

Location Name: CUNDIFF FEDERAL GU B-N35N7W Number: 19NESE County: LA PLATA
Qtrqr: NESE Sec: 19 Twp: 35N Range: 7W Meridian: N
Latitude: 37.283773 Longitude: -107.672677

FACILITY - API Number: 05-067-00 Facility ID: 215569

Facility Name: CUNDIFF FEDERAL B Number: 1
Qtrqr: NESE Sec: 19 Twp: 35N Range: 7W Meridian: N
Latitude: 37.283773 Longitude: -107.672677

CORRECTIVE ACTIIONS:

1 CA# 134501

Corrective Action: Stormwater and erosion controls need to be installed to stabilize erosion on the northeastern cut-slope. Date: 11/29/2019

Response: CA COMPLETED Date of Completion: 04/06/2020

Operator Comment: Deadlines unattainable due to winter weather conditions of high precipitation content in soils and frozen ground conditions. Location cut slope has been seeded with 100% biodegradable erosion blanket installed after seeding. See attached.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Deadlines unattainable due to winter weather conditions of high precipitation content in soils and frozen ground conditions. Location cut slope has been seeded with 100% biodegradable erosion blanket installed after seeding. See attached

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: _____

Title: Specialist

Date: 4/6/2020 4:32:28 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
402363451	FIR RESOLUTION SUBMITTED
402363470	Work Completion photos

Total Attach: 2 Files