

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402369400

Date Received:

04/13/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000

Name of Operator: BP AMERICA PRODUCTION COMPANY

Address: 1199 MAIN AVENUE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Beebe, Sabre

sabre.beebe@bpx.com

SanJuanCOGCC@bp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693901078

Inspection Date: 11/06/2019

FIR Submit Date: 11/13/2019

FIR Status: _____

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY

Company Number: 10000

Address: 1199 MAIN AVENUE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 325907

Location Name: HUMISTON FEDERAL GU- Number: 33NESE County: LA PLATA
N35N7W

Qtrqtr: NESE Sec: 33 Twp: 35N Range: 7W Meridian: N

Latitude: 37.255717 Longitude: -107.635581

FACILITY - API Number: 05-067- -00 Facility ID: 215548

Facility Name: HUMISTON FEDERAL Number: 1

Qtrqtr: NESE Sec: 33 Twp: 35N Range: 7W Meridian: N

Latitude: 37.255717 Longitude: -107.635581

CORRECTIVE ACTIONS:

1 ☒ CA# 134487

Corrective Action: Control weeds.

Date: 11/29/2019

Response: CA COMPLETED

Date of Completion: 04/06/2020

Operator
Comment:

Manual weed removal performed additional treatment scheduled for 2020

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 ☒ CA# 134488

Corrective Action: Stormwater and erosion controls are needed to stabilize erosion on the well pad cut-slope. Stormwater controls need to be selected, sized, installed, and maintained using good engineering practices such as those described in CDOT manuals for erosion control. These controls need to be maintained in good condition until the cut-slope is stabilized with desirable perennial vegetation.

Date: 11/29/2019

Response: CA COMPLETED

Date of Completion: 04/08/2020

Operator
Comment: Seeding of cut slope with installation of 100% biodegradable erosion blanket installation completed.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions addressed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: _____

Title: Specialist

Date: 4/13/2020 2:34:14 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402369400	FIR RESOLUTION SUBMITTED
402369416	Work completion photos

Total Attach: 2 Files