

FORM  
INSPRev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/23/2020

Submitted Date:

04/27/2020

Document Number:

687400787

### FIELD INSPECTION FORM

Loc ID 320278 Inspector Name: Huck, Keith On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1675 BROADWAY, STE 2800  
City: DENVER State: CO Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 11 Number of Comments  
2 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203334	WELL	PR	12/01/2019	OW	001-08843	BOX ELDER 27-1	SI

**General Comment:**

**Location**

Overall Good:

**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Amount missing on production tank		
Corrective Action:	Install sign to comply with Rule 210.d.. Corrective Action Date:05/25/2020. See attached photo#2	Date:	05/25/2020
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Adequate		
Corrective Action:		Date:	

**Good Housekeeping:**

Type	DEBRIS		
Comment:	Deed weeds all around tak battery.		
Corrective Action:	Location is within a designated setback location, remove trash or debris per Rule 604.c. (2)P. Corrective Action Date:05/08/2020. See attached photo#1	Date:	05/08/2020

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	Pipe		
Corrective Action:		Date:	

**Equipment:**

Type:		#		corrective date
Plunger Lift		# 1		
Comment:				
Corrective Action:				Date:
Emission Control Device		# 1		
Comment:				
Corrective Action:				Date:
Bradenhead		# 1		
Comment:	Appears to be plumbed to surface			

Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		39.931368,-104.654586
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Shares berm with production tank			
Corrective Action:				Date:

**Venting:**

Yes/No	NO
Comment:	

Corrective Action:		Date:	
--------------------	--	-------	--

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 203334 Type: WELL API Number: 001-08843 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: SI

Corrective Action:  Date:

**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary</b>                      On (Thursday) at approximately (10:37am), I, Inspector (Keith Huck), conducted an on-site inspection at (Box Elder 27-1) (KPK), at (Location#320278) in (Adams,County) Colorado. While there, I observed (Production.) During this inspection the following possible compliance issues were observed: Location is within a designated setback location, remove trash or debris per Rule 604.c. (2)P. Corrective Action Date05/08/2020. See attached photo#1</p> <p>Install sign to comply with Rule 210.d.. Corrective Action Date:05/25/2020. See attached photo#2</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	huckk	04/27/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687400788	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5133525">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5133525</a>