

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402383983

Date Received:
04/29/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672
Name of Operator: TIMBER CREEK OPERATING LLC
Address: 6295 GREENWOOD PLAZA BLVD #100
City: GREENWOOD VILLAGE State: CO Zip: 8111-4978
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>BAKER DAVID</u>		<u>dbaker@auroramp.com</u>
<u>Mack, Ronald</u>		<u>ronaldmack@tcenergyllc.com</u>
<u>Fitzgerald, Edie</u>	<u>719-859-1394</u>	<u>ediefitzgerald@tcenergyllc.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 689901894
Inspection Date: 03/12/2020 FIR Submit Date: 03/16/2020 FIR Status: _____

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC Company Number: 10672
Address: 6295 GREENWOOD PLAZA BLVD #100
City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

LOCATION - Location ID: 308907

Location Name: HILL RANCH-634S67W Number: 27SWNE County: LAS ANIMAS
Qtrqtr: SWNE Sec: 27 Twp: 34S Range: 67W Meridian: 6
Latitude: 37.055309 Longitude: -104.874309

FACILITY - API Number: 05-071-00 Facility ID: 284776

Facility Name: HILL RANCH Number: 27-7
Qtrqtr: SWNE Sec: 27 Twp: 34S Range: 67W Meridian: 6
Latitude: 37.055309 Longitude: -104.874309

CORRECTIVE ACTIONS:

1 CA# 137235

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C Date: 04/24/2020
Response: CA COMPLETED Date of Completion: 04/10/2020

All erosion control implemented along the main lease road and the access road of the well pad were completed on 04/10/20 with the exception of the ditch erosion depicted on photo 8 of the field inspection report 689901894.

Operator Comment: The operator missed that portion of the corrective action and the equipment was dispatched to a different location. The ditch erosion parallel to the main lease road at LAT. 37.05713 LONG.-104.87836 was addressed and corrected on 04/28/20. See attached photo log for details.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions have been addressed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed: _____

Title: SR. Environmental Tech.

Date: 4/29/2020 8:10:07 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402384013	Photo Log
-----------	-----------

Total Attach: 1 Files