

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402383983

Date Received:

04/29/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672

Name of Operator: TIMBER CREEK OPERATING LLC

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

BAKER DAVID

dbaker@auroramp.com

Mack, Ronald

ronaldmack@tcenergyllc.com

Fitzgerald, Edie

719-859-1394

ediefitzgerald@tcenergyllc.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 689901894

Inspection Date: 03/12/2020

FIR Submit Date: 03/16/2020

FIR Status: _____

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC

Company Number: 10672

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

LOCATION - Location ID: 308907

Location Name: HILL RANCH-634S67W Number: 27SWNE County: LAS ANIMAS

Qtrqtr: SWNE Sec: 27 Twp: 34S Range: 67W Meridian: 6

Latitude: 37.055309 Longitude: -104.874309

FACILITY - API Number: 05-071- -00 Facility ID: 284776

Facility Name: HILL RANCH Number: 27-7

Qtrqtr: SWNE Sec: 27 Twp: 34S Range: 67W Meridian: 6

Latitude: 37.055309 Longitude: -104.874309

CORRECTIVE ACTIONS:

1 ☒ CA# 137235

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 04/24/2020

Response: CA COMPLETED

Date of Completion: 04/10/2020

Operator Comment: All erosion control implemented along the main lease road and the access road of the well pad were completed on 04/10/20 with the exception of the ditch erosion depicted on photo 8 of the field inspection report 689901894. The operator missed that portion of the corrective action and the equipment was dispatched to a different

location. The ditch erosion parallel to the main lease road at LAT. 37.05713 LONG.-104.87836 was addressed and corrected on 04/28/20. See attached photo log for details.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions have been addressed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed: _____

Title: SR. Environmental Tech.

Date: 4/29/2020 8:10:07 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402383983	FIR RESOLUTION SUBMITTED
402384013	Photo Log

Total Attach: 2 Files