

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402388687

Date Received:

05/04/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Shorty, Priscilla</u>		<u>pshorty@hilcorp.com</u>
<u>Ray, Mandy</u>	<u>(505) 599-4083</u>	<u>mray@hilcorp.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693901573

Inspection Date: 03/24/2020

FIR Submit Date: 03/27/2020

FIR Status: _____

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY

Company Number: 10133

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 325249

Location Name: ALLISON UNIT-N32N6W Number: 19NWSW County: LA PLATA

Qtrqr: NWS Sec: 19 Twp: 32N Range: 6W Meridian: N
W

Latitude: 37.002740 Longitude: -107.548080

FACILITY - API Number: 05-067- -00 Facility ID: 214397

Facility Name: ALLISON UNIT Number: 25

Qtrqr: NWS Sec: 19 Twp: 32N Range: 6W Meridian: N
W

Latitude: 37.002740 Longitude: -107.548080

CORRECTIVE ACTIONS:

1 CA# 137537

Corrective Action: Remove waste and debris.

Date: 04/30/2020

Response: CA COMPLETED

Date of Completion: 05/04/2020

Operator
Comment: Cement debris removed

COGCC Decision: _____

COGCC
Representative:

2 CA# 137538

Corrective Action: Mark or remove guyline anchors.

Date: 04/30/2020

Response: CA COMPLETED

Date of Completion: 05/04/2020

Operator
Comment:

Rig anchors marked

COGCC Decision: _____

COGCC
Representative:

3 CA# 137539

Corrective Action: Revegetation needs to be conducted within the interim reclamation areas. See stormwater section below for erosion control/mulching requirements. Revegetation needs to be installed with plant species representative of reference areas.

Date: 04/30/2020

Response: CA COMPLETED

Date of Completion: 05/04/2020

Operator
Comment:

Revegetation with mulch is completed

COGCC Decision: _____

COGCC
Representative:

4 CA# 137540

Corrective Action: Stormwater controls (BMPs) need to be installed to stabilize erosion within the project area.
Erosion controls (ie: mulch, blankets, etc.) need to be installed and maintained until location is stabilized with desirable perennial vegetation. Livestock exclusion will likely need to be installed for successful vegetation establishment.

Date: 04/30/2020

Response: CA COMPLETED

Date of Completion: 05/04/2020

Operator
Comment:

Revegetation with mulch is completed

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Mandi Walker

Signed: _____

Title: Operation/Regulatory Tech

Date: 5/4/2020 1:04:54 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402388692	Allison Unit 25
402388695	Allison Unit 25

Total Attach: 2 Files