

APACHE CANYON 12-05 API# 05-071-06170 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 30, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695102494



PHOTO 1: MAINTENANCE WAS CONDUCTED TO STOP THE LEAK. THE FLUID ACCUMULATION WAS REMOVED FROM THE LIQUID RING COMPRESSOR SKID AND RESERVOIR. THE IMPACTED SOIL/GRAVEL NEXT TO THE LIQUID RING COMPRESSOR WAS REMOVED FROM THE LOCATION.

APACHE CANYON 12-05 API# 05-071-06170 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 30, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695102494



PHOTO 2: THE IMPACTED SOIL/GRAVEL NEAR THE LIQUID RING COMPRESSOR WAS REMOVED AND THE LEAK WAS REPAIRED.

APACHE CANYON 12-05 API# 05-071-06170 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 30, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695102494



PHOTO 4: THE FLUID ACCUMULATION WAS REMOVED FROM THE LIQUID RING COMPRESSOR SKID AND RESERVOIR. THE IMPACTED SOIL/GRAVEL NEXT TO THE LIQUID RING COMPRESSOR WAS REMOVED FROM THE LOCATION.

APACHE CANYON 12-05 API# 05-071-06170 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 30, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695102494



PHOTO 4: REPAIR ARE COMPLETE ON THE LIQUID RING COMPRESSOR