

APACHE CANYON 12-02V API# 05-071-07407 – TIMBER CREEK OPERATING  
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 30, 2020  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695102485



PHOTO 1: THE FLUID ACCUMULATION WAS REMOVED FROM THE LIQUID RING COMPRESSOR CONTAINMENT SKID.

APACHE CANYON 12-02V API# 05-071-07407 – TIMBER CREEK OPERATING  
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 30, 2020  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695102485



PHOTO 2: THE IMPACTED SOIL/GRAVEL NEAR THE LIQUID RING COMPRESSOR WAS REMOVED AND THE LEAK WAS REPAIRED.

APACHE CANYON 12-02V API# 05-071-07407 – TIMBER CREEK OPERATING  
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 30, 2020  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695102485



PHOTO 3: THE (2) RISER'S ARE LOW POINT AND HIGH POINT DRAIN'S WHICH ARE IN USE. THE RISER'S WERE LABELED AS TO THE FUNCTION FOR CLARITY.

APACHE CANYON 12-02V API# 05-071-07407 – TIMBER CREEK OPERATING  
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 30, 2020  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695102485



PHOTO 4: THE LEAK ON THE LIQUID RING COMPRESSOR WAS REPAIRED AND THE CONTAINMENT WAS CLEANED UP.