



spill 468756

40.131730, -104.796256 looking northwest

impacted soils mound has no erosion controls on downhill side

to minimize migration of impacted materials

or physical controls to minimize access to impacted materials by wildlife, livestock or humans

5.5.2020 08:49