

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402393800  
Date Received:  
05/08/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10679

Name of Operator: LOGOS OPERATING LLC

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87415

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

| Contact Name           | Phone | Email                                  |
|------------------------|-------|--|
| <u>Marie Florez</u>    |       | <u>mflorez@logosresourcesllc.com</u>   |
| <u>Sessions, Tamra</u> |       | <u>tsessions@logosresourcesllc.com</u> |
| <u>Rowley, Darren</u>  |       | <u>drowley@logosresourcesllc.com</u>   |

COGCC INSPECTION SUMMARY:

FIR Document Number: 693901630

Inspection Date: 04/08/2020

FIR Submit Date: 04/10/2020

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: LOGOS OPERATING LLC

Company Number: 10679

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87415

LOCATION - Location ID: 325157

Location Name: IGNACIO 33-7-N33N7W Number: 7NWSE County: LA PLATA

Qtrqr: NWSE Sec: 7 Twp: 33N Range: 7W Meridian: N

Latitude: 37.115600 Longitude: -107.647520

FACILITY - API Number: 05-067-00 Facility ID: 214152

Facility Name: IGNACIO 33-7 Number: 7

Qtrqr: NWSE Sec: 7 Twp: 33N Range: 7W Meridian: N

Latitude: 37.115600 Longitude: -107.647520

CORRECTIVE ACTIONS:

1 CA# 137903

Corrective Action: Remove and properly dispose of Russian thistle debris.

Date: 05/11/2020

Response: CA COMPLETED

Date of Completion: 04/30/2020

Operator Comment: A contractor working For LOGOS Operating performed interim reclamation work at the Ignacio 33-7#7 on 4/30/2020. This included the disposal of Russian thistle debris and installing storm water BMP's, recontouring, decompacting, and revegetating the areas not needed for production operations. The location was mulched to assist with successful revegetation. Additional detail provided in attached photos.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**2** CA# 137904

Corrective Action: Revegetation needs to be conducted in portions of the interim reclamation area with poor revegetation.

Date: 05/15/2020

Response: CA COMPLETED

Date of Completion: 04/30/2020

Operator  
Comment:

A contractor working For LOGOS Operating performed interim reclamation work at the Ignacio 33-7#7 on 4/30/2020. This included the disposal of Russian thistle debris and installing storm water BMP's, recontouring, decompacting, and revegetating the areas not needed for production operations. The location was mulched to assist with successful revegetation. Additional detail provided in attached photos.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**3** CA# 137905

Corrective Action: -Erosion controls (such as mulch) and stormwater BMPs are needed throughout the interim reclamation area by 5/15/2020, and maintained until stabilized with desirable perennial vegetation.

Date: 05/15/2020

Response: CA COMPLETED

Date of Completion: 04/30/2020

Operator  
Comment:

A contractor working For LOGOS Operating performed interim reclamation work at the Ignacio 33-7#7 on 4/30/2020. This included the disposal of Russian thistle debris and installing storm water BMP's, recontouring, decompacting, and revegetating the areas not needed for production operations. The location was mulched to assist with successful revegetation. Additional detail provided in attached photos.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: A contractor working For LOGOS Operating performed interim reclamation work at the Ignacio 33-7#7 on 4/30/2020. This included the disposal of Russian thistle debris and installing storm water BMP's, recontouring, decompacting, and revegetating the areas not needed for production operations. The location was mulched to assist with successful revegetation. Additional detail provided in attached photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tamra Sessions

Signed: \_\_\_\_\_

Title: Regulatory Specialist

Date: 5/8/2020 1:26:24 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

| <u>Document Number</u> | <u>Description</u>               |
|------------------------|----------------------------------|
| 402393803              | Reclamation with seeding/mulch#1 |
| 402393810              | Reclamation with seeding/mulch#2 |
| 402393817              | Reclamation with seeding/mulch#3 |

Total Attach: 3 Files