

Inspection Photos
Operator Name: TEP Rocky Mountain LLC
Location: 335045



Existing 2" carbon steel Flowlines was taken out of service and will be plugged and abandoned when location is reclaimed. Flowline was capped and cut 3' under dirt grade

Inspection Photos
Operator Name: TEP Rocky Mountain LLC
Location: 335045



New 2" stainless steel risers installed with tracer wire

Inspection Photos
Operator Name: TEP Rocky Mountain LLC
Location: 335045



New Shawcor 2"FP301W flowlines installed and tested