

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/06/2020

Submitted Date:

05/14/2020

Document Number:

688000449**FIELD INSPECTION FORM**Loc ID 311869 Inspector Name: YOUNG, ROB On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 94300Name of Operator: WARD & SON* ALFREDAddress: P O BOX 737City: OGALLALLA State: NE Zip: 69153**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Ward, Randy	(308) 280-0100	randy@wardoil.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
107663	PIT	AC			-	COLORADO "B"	EI

General Comment:

Environmental inspection related to Rem #8073, Former oil skim pit remediation. Impacted soil stockpile remains on site and is accumulating impacted soil from other locations. Remove and properly dispose the soil stockpile immediately.

Environmental**Waste Management:**

Type	Management	Condition	GPS (Lat)	(Long)
Oily Soil	Piles	Inadequate		
Comment:	Impacted soil stockpile remains on location east of the open pit remediation. Soil stockpile requires immediate off site disposal at a commercial landfill.			
Corrective Action:	Immediately remove the impacted soil stockpile and transport to a commercial landfill for proper disposal per Rule 907.e. and 907.b.(1). CA date from 3/29/2019 FI 688000305 (5/24/2019) remains in effect.			Date: 05/24/2019

Spill/Remediation:

Comment:	Oil impacted soil has not been laterally defined in the open excavation. It is likely that the vertical separator will require removal/relocation to allow for adequate excavation to the north and along the east side of the excavation.			
Corrective Action:	Submit an eForm 27 outlining plans to adequately assess and or remediate oil impacted soils in the excavation to allow for project closure.			Date: 05/29/2020

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688000450	Location photographs	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5151213