

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/13/2020

Submitted Date:

05/14/2020

Document Number:

689704696

**FIELD INSPECTION FORM**

Loc ID 334884 Inspector Name: LONGWORTH, MIKE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: PO BOX 370  
City: PARACHUTE State: CO Zip: 81635

**Findings:**

- 8 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	
Byers, Jim		jbyers@blm.gov	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211371	WELL	PR	10/10/1997	GW	045-07131	FEDERAL GM 42-4	PR
273022	WELL	PR	11/20/2005	GW	045-10209	FEDERAL GM 342-4	PR
273023	WELL	PR	11/18/2005	GW	045-10207	FEDERAL GM 442-4	PR
273024	WELL	PR	11/14/2005	GW	045-10206	FEDERAL GM 542-4	PR

**General Comment:**

I, Inspector Mike Longworth, conducted an inspection on site.  
During this inspection the following possible compliance issues were observed:  
Tank capacity on label on 300 bbl tank is too small and faded to read at distance.  
Install sign to comply with Rule 210.d.  
C.A. Date 08/15/2020  
Washing and riling around separators. Channeling through berm at entrance of location.  
Install or repair required BMPs per Rule 1002.f.(2)C  
C.A. Date 05/30/2020  
A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action:			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Tank capacity on label on 300 bbl tank is too small and faded to read at distance. Install sign to comply with Rule 210.d.		
Corrective Action:	Install sign to comply with Rule 210.d.		Date: 08/15/2020

<b>Emergency Contact Number:</b>			
Comment:	911		
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	TRASH		
Comment:			
Corrective Action:			Date:

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	<u>211371</u>	Type:	<u>WELL</u>	API Number:	<u>045-07131</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Producing well</u>								
Corrective Action:						Date:			
Facility ID:	<u>273022</u>	Type:	<u>WELL</u>	API Number:	<u>045-10209</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Producing well</u>								
Corrective Action:						Date:			
Facility ID:	<u>273023</u>	Type:	<u>WELL</u>	API Number:	<u>045-10207</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Producing well</u>								
Corrective Action:						Date:			
Facility ID:	<u>273024</u>	Type:	<u>WELL</u>	API Number:	<u>045-10206</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Producing well</u>								
Corrective Action:						Date:			

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Washing and riling around separators. Channeling through berm at entrance of location.](#)  
[Install or repair required BMPs per Rule 1002.f.\(2\)C](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.\(2\)C](#)

Date: 05/30/2020

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689704697	Inspection 689704696 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5151352">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5151352</a>