

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/14/2020

Submitted Date:

05/14/2020

Document Number:

699801102

FIELD INSPECTION FORM

Loc ID: 312472 Inspector Name: De Paolo, Corey On-Site Inspection: 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Findings:

1 Number of Comments

0 Number of Corrective Actions

Corrective Action Response Requested

Operator Information:

OGCC Operator Number: 53255

Name of Operator: MARALEX RESOURCES INC

Address: P O BOX 338

City: IGNACIO State: CO Zip: 81137

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
Murray, Richard		g.richard.murray@state.co.us	
Jordan, Reid		maralextechjr@gmail.com	
Graves, Jim		mrinc20@maralexinc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
475647	Domestic Tap	AC	04/23/2020		-	Domestic Tap 18SEnw	AC

General Comment:

COGCC Inspection Report Summary
 On Thursday 5/14/20 at approximately 13:00 hours, I, Inspector Corey De Paolo, Conducted an on-site inspection at MARALEX RESOURCES INC Domestic Tap /18SEnw, Location #475647 in Mesa County Colorado.
 Refer to location #312472 for inventory, inspections and all other documents.
 The domestic tap is derived from sales line. See photo #1192. The pressure is first regulated by a Fisher Big Joe regulator with a maximum operational pressure drop of 1500 psi and a maximum outlet pressure of 150 psi. See photo #1194. Downstream of the big joe regulator is a scrubber pot for fluid knock out. See photo #1195. The pressure is then regulated by a Fisher Little Joe with an operational pressure range of 15 to 40 psi. See photo #1193. The fittings up stream of the regulators appear to be 1000 to 2000 psi rated fittings. The cast fittings down steam of the regulators appear to be sufficient to support the maximum operational pressure of the secondary regulator of 40 psi. The domestic tap supplies the house to the North of location. No address on record. Refer to document #402217411 for point of origin and point of delivery.
 This is a summary of inspection report.

Inspected Facilities

Facility ID: 475647 Type: Domestic Tap API Number: - Status: AC Insp. Status: AC

Producing Well

Comment:		
Corrective Action:		Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699801103	Photos for Insp. #699801102	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5151389