

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402399506

Date Received:  
05/15/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672  
Name of Operator: TIMBER CREEK OPERATING LLC  
Address: 6295 GREENWOOD PLAZA BLVD #100  
City: GREENWOOD VILLAGE State: CO Zip: 8111-4978  
Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Mack, Ronald</u>		<u>ronaldmack@tcenergyllc.com</u>
<u>Santistevan, Vince</u>	<u>719-845-2102/719-680-9705</u>	<u>vincasantistevan@tcenergyllc.com</u>
<u>Fitzgerald, Edie</u>	<u>719-859-1394</u>	<u>ediefitzgerald@tcenergyllc.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 695102491  
Inspection Date: 03/31/2020 FIR Submit Date: 03/31/2020 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC Company Number: 10672  
Address: 6295 GREENWOOD PLAZA BLVD #100  
City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

LOCATION - Location ID: 308596

Location Name: APACHE CANYON-634S67W Number: 7SENE County: LAS ANIMAS  
Qtrqr: SENE Sec: 7 Twp: 34S Range: 67W Meridian: 6  
Latitude: 37.099390 Longitude: -104.923920

FACILITY - API Number: 05-071- -00 Facility ID: 275758

Facility Name: APACHE CANYON Number: 7-08  
Qtrqr: SENE Sec: 7 Twp: 34S Range: 67W Meridian: 6  
Latitude: 37.099390 Longitude: -104.923920

CORRECTIVE ACTIONS:

1 CA# 137633

Corrective Action: Conduct maintenance on equipment, cleanup stained material and review self inspection processes.

Date: 04/30/2020

Response: CA COMPLETED

Date of Completion: 05/14/2020

Operator Comment: Maintenance was performed on the liquid ring compressor to stop the leak. The fluid accumulation in the containment of the compressor was removed and the skid was cleaned up. The impacted soil surrounding the liquid ring was removed from location. See attached photo log for details.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

2 CA# 137634

Corrective Action: COMPLY WITH GENERAL PERVISIONS OF OIL AND GAS ACT & SB-181 PERTAINING TO WILDLIFE PROTECTION.

Date: 04/30/2020

Response: CA COMPLETED

Date of Completion: 05/14/2020

Operator Comment: Maintenance was performed on the liquid ring compressor to stop the leak. The fluid accumulation in the containment of the compressor was removed and the skid was cleaned up. The impacted soil surrounding the liquid ring was removed from location. See attached photo log for details.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

#### OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective actions have been addressed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed: \_\_\_\_\_

Title: SR. Environmental Tech.

Date: 5/15/2020 10:22:08 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402399509	Photo Log
-----------	-----------

Total Attach: 1 Files