

APACHE CANYON 07-08 API# 05-071-08300 – TIMBER CREEK OPERATING  
OGCC OPERATOR NUMBER 10672 - DATE: MAY 14, 2020  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695102491



PHOTO 1: THE LEAK ON THE LIQUID RING ENGINE WAS REPAIRED AND THE FLUID ACCUMULATION WAS REMOVED FROM THE COMPRESSOR CONTAINMENT.

APACHE CANYON 07-08 API# 05-071-08300 – TIMBER CREEK OPERATING  
OGCC OPERATOR NUMBER 10672 - DATE: MAY 14, 2020  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695102491



PHOTO 2: THE IMPACTED SOIL/GRAVEL SURROUNDING THE LIQUID RING COMPRESSOR WAS CLEANED UP AND REMOVED FROM THE LOCATION.



APACHE CANYON 07-08 API# 05-071-08300 – TIMBER CREEK OPERATING  
OGCC OPERATOR NUMBER 10672 - DATE: MAY 14, 2020  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695102491



PHOTO 3: THE IMPACTED SOIL/GRAVEL SURROUNDING THE LIQUID RING COMPRESSOR WAS CLEANED UP AND REMOVED FROM THE LOCATION.