

APACHE CANYON 29-06 API# 05-071-09288 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: MAY 14, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690200131



PHOTO 1: FACING SOUTHEAST ALONG THE MAIN LEASE ROAD IN LITTLE BINGHAM CANYON. THE SEDIMENT ACCUMULATION WAS REMOVED FROM THE CULVERT INLET.

APACHE CANYON 29-06 API# 05-071-09288 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: MAY 14, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690200131



PHOTO 2: THE SEDIMENT ACCUMULATION WAS REMOVED FROM THE CULVERT INLET.

APACHE CANYON 29-06 API# 05-071-09288 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: MAY 14, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690200131



PHOTO 3: THE EROSION ON THE CULVERT OUTLET WAS BACKFILLED.

APACHE CANYON 29-06 API# 05-071-09288 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: MAY 14, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690200131



PHOTO 4: AN ADDITIONAL CULVERT WAS INSTALLED ON THE MAIN LEASE ROAD IN BIG BINGHAM CANYON.