

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/15/2020

Submitted Date:

05/15/2020

Document Number:

696102979

FIELD INSPECTION FORM

Loc ID 330166 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Findings:

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections
,		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
250733	WELL	SI	06/01/2017	OW	123-18536	WARDLAW 35-21	SI

General Comment:

This is an Alternate Method Inspection | AMI.
Well(s): 1: Temporarily Abandoned | TA.
Battery: Inactive | Shut-down.

Centralized Battery serves 3 Location IDs (331974, 330167, 330166).
(Well(s): 2: Shut-In | SI ; 1: Temporarily Abandoned | TA).

Centralized Battery formerly served 1 Location ID (329660).
(Well(s): 1: Plugged & Abandoned | PA).

Refer to Field Inspection Doc. #696102777 and/or Location ID #330166 for Battery / Facility, Equipment info.

Follow-up to Field Inspection Report Doc. #696102777 dated 04/22/2020.
This inspection only comprises the mitigation of prior inspection Corrective Actions.

Inspected Facilities

Facility ID: 250733 Type: WELL API Number: 123-18536 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
Well disconnected from flowline.
Yellow LTSI tag posted at well.
Locked-Out, Tagged-Out | LOTO.
COGCC records indicate last production: 05/2017.
SI/TA well per Alternative Mechanical Integrity Assurance Program (Alternative Program). Doc #02385001 (NOBLE).

Prior insp:
Well is overdue for Mechanical Integrity Test.
MIT requires 10-day notification via Form 42.
Well plugging requires an approved Form 6 Intent to Abandon to Plug Well.
Refer to Rule 326.b.
Corrective Action:
Produce well after performing successful mechanical integrity test per Rule 326 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention.
Refer to Rule 326.b.
Corrective Action Date: 07/21/2020. Extended due to COVID.

This insp:
* This is a SI/TA well per Alternative Mechanical Integrity Assurance Program (Alternative Program). Doc #02385001 (NOBLE).
This mitigates the Corrective Action for Delinquent MIT.

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On FRI 05/15/2020 at approximately 13:30 hrs. I, Bret Evins, conducted an Alternate Method Inspection AMI at: Operator Name: NOBLE ENERGY INC Location Name: WARDLAW-66N64W /35NENW Location ID: 330166 Well Name: Wardlaw 35-21 API: 05-123-18536 Location County: Weld County, Colorado Weather: Partlly cloudy, dry.</p> <p>Observations from prior on-site inspection: While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Inactive Shut-down.</p> <p>Centralized Battery serves 3 Location IDs (331974, 330167, 330166). (Well(s): 2: Shut-In SI ; 1: Temporarily Abandoned TA).</p> <p>Centralized Battery formerly served 1 Location ID (329660). (Well(s): 1: Plugged & Abandoned PA).</p> <p>Refer to Field Inspection Doc. #696102777 and/or Location ID #330166 for Battery / Facility, Equipment info.</p> <p>Follow-up to Field Inspection Report Doc. #696102777 dated 04/22/2020. This inspection only comprises the mitigation of prior inspection Corrective Actions.</p> <p>During this inspection, the following prior possible compliance issues appear to be addressed: 1.) Well is overdue for Mechanical Integrity Test. MIT requires 10-day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to Plug Well. Refer to Rule 326.b. Corrective Action: Produce well after performing successful mechanical integrity test per Rule 326 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention. Refer to Rule 326.b. Corrective Action Date: 07/21/2020. Extended due to COVID. * This is a SI/TA well per Alternative Mechanical Integrity Assurance Program (Alternative Program). Doc #02385001 (NOBLE). This mitigates the Corrective Action for Delinquent MIT.</p> <p>NO: New / Current possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	05/15/2020