

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/15/2020

Submitted Date:

05/15/2020

Document Number:

696102980

FIELD INSPECTION FORMLoc ID 330167 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
250734	WELL	SI	06/01/2017	GW	123-18537	WARDLAW 35-22	SI

General Comment:

This is an Alternate Method Inspection | AMI.

Well(s): 1: Shut-In | SI.

Battery: Inactive | Shut-down.

Centralized Battery serves 3 Location IDs (331974, 330167, 330166).

(Well(s): 2: Shut-In | SI ; 1: Temporarily Abandoned | TA).

Centralized Battery formerly served 1 Location ID (329660).

(Well(s): 1: Plugged & Abandoned | PA).

Refer to Field Inspection Report doc. #696102777 and/or Location ID #330166
for Battery / Facility, Equipment info.

Follow-up to Field Inspection Report Doc. #696102781 dated 04/22/2020.

This inspection only comprises the mitigation of prior inspection Corrective Actions.

Inspected FacilitiesFacility ID: 250734 Type: WELL API Number: 123-18537 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: PRODUCTION RECORDSComment:

Shut-In | SI.

Yellow LTSI tag posted at well.

Locked-Out, Tagged-Out | LOTO.

COGCC records indicate last production: 05/2017.

SI/TA well per Alternative Mechanical Integrity Assurance Program (Alternative Program). Doc #02385001 (NOBLE).

Prior insp:

Well is overdue for Mechanical Integrity Test.

MIT requires 10-day notification via Form 42.

Well plugging requires an approved Form 6 Intent to Abandon to Plug Well.

Refer to Rule 326.b.

Corrective Action:

Produce well after performing successful mechanical integrity test per Rule 326 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention.

Refer to Rule 326.b.

Corrective Action Date: 07/21/2020. Extended due to COVID.

This insp:

* This is a SI/TA well per Alternative Mechanical Integrity Assurance Program (Alternative Program). Doc #02385001 (NOBLE).

This mitigates the Corrective Action for Delinquent MIT.

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On FRI 05/15/2020 at approximately 14:00 hrs. I, Bret Evins, conducted an Alternate Method Inspection AMI at: Operator Name: NOBLE ENERGY INC Location Name: WARDLAW-66N64W /35NWNW Location ID: 330167 Well Name: Wardlaw 35-22 API: 05-123-18537 Location County: Weld County, Colorado Weather: Partltly cloudy, dry.</p> <p>Observations from prior on-site inspection: While there, I observed: Well(s): 1: Shut-In SI. Battery: Inactive Shut-down.</p> <p>Centralized Battery serves 3 Location IDs (331974, 330167, 330166). (Well(s): 2: Shut-In SI ; 1: Temporarily Abandoned TA).</p> <p>Centralized Battery formerly served 1 Location ID (329660). (Well(s): 1: Plugged & Abandoned PA).</p> <p>Refer to Field Inspection Doc. #696102777 and/or Location ID #330166 for Battery / Facility, Equipment info.</p> <p>Follow-up to Field Inspection Report Doc. #696102781 dated 04/22/2020. This inspection only comprises the mitigation of prior inspection Corrective Actions.</p> <p>During this inspection, the following prior possible compliance issues appear to be addressed: 1.) Well is overdue for Mechanical Integrity Test. MIT requires 10-day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to Plug Well. Refer to Rule 326.b. Corrective Action: Produce well after performing successful mechanical integrity test per Rule 326 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention. Refer to Rule 326.b. Corrective Action Date: 07/21/2020. Extended due to COVID. * This is a SI/TA well per Alternative Mechanical Integrity Assurance Program (Alternative Program). Doc #02385001 (NOBLE). This mitigates the Corrective Action for Delinquent MIT.</p> <p>NO: New / Current possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	05/15/2020