

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402392289

Date Received:  
05/07/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672  
Name of Operator: TIMBER CREEK OPERATING LLC  
Address: 6295 GREENWOOD PLAZA BLVD #100  
City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Santistevan, Vince</u>	<u>719-845-2102/719-680-9705</u>	<u>vincasantistevan@tcenergyllc.com</u>
<u>Mack, Ronald</u>		<u>ronaldmack@tcenergyllc.com</u>
<u>Fitzgerald, Edie</u>	<u>719-859-1394</u>	<u>ediefitzgerald@tcenergyllc.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 695102765  
Inspection Date: 04/30/2020 FIR Submit Date: 05/01/2020 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC Company Number: 10672  
Address: 6295 GREENWOOD PLAZA BLVD #100  
City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

LOCATION - Location ID: 309440

Location Name: NEW ELK-633S68W Number: 25NWNW County: LAS ANIMAS  
Qtrqtr: NWN Sec: 25 Twp: 33S Range: 68W Meridian: 6  
W  
Latitude: 37.147144 Longitude: -104.951726

FACILITY - API Number: 05-071-00 Facility ID: 295029

Facility Name: NEW ELK Number: 25-04  
Qtrqtr: NWN Sec: 25 Twp: 33S Range: 68W Meridian: 6  
W  
Latitude: 37.147144 Longitude: -104.951726

CORRECTIVE ACTIONS:

1  CA# 138569  
Corrective Action: REMOVE UNUSED EQUIPMENT COMPLY WITH RULE 603.F. Date: 05/09/2020  
Response: CA COMPLETED Date of Completion: 05/06/2020

Operator Comment: The unused automation pole was removed from the location. See attached photo log for details.

COGCC Decision: Approved via an AMI

COGCC Representative: CA APPROVED BASED ON PHOTOS SUBMITTED IN THIS DOCUMENT.

**2**  CA# 138570

Corrective Action: Conduct maintenance on equipment, cleanup stained material and review self inspection processes. (REMOVE ALL IMPACTED SOIL ON LOCATION). Date: 05/07/2020

Response: CA COMPLETED Date of Completion: 05/06/2020

Operator Comment: Maintenance was conducted to stop the leak on the liquid ring compressor. The impacted soil around the liquid ring was removed from location. See attached photo log for details.

COGCC Decision: Approved via an AMI

COGCC Representative: CA APPROVED BASED ON PHOTOS SUBMITTED IN THIS DOCUMENT.

**3**  CA# 138571

Corrective Action: REMOVE ALL TRASH IN AND AROUND LOCATION. COMPLY WITH RULE603.F. Date: 05/09/2020

Response: CA COMPLETED Date of Completion: 05/06/2020

Operator Comment: The discarded material was collected and removed from the location.

COGCC Decision: Approved via an AMI

COGCC Representative: CA APPROVED BASED ON PHOTOS SUBMITTED IN THIS DOCUMENT.

**4**  CA# 138572

Corrective Action: Comply with general provisions of the oil and gas act for wildlife protection. Date: 05/07/2020

Response: CA COMPLETED Date of Completion: 05/06/2020

Operator Comment: The fluid accumulation in the containment of the liquid ring compressor was removed and the skid was cleaned up. See attached photo log for details.

COGCC Decision: Approved via an AMI

COGCC Representative: CA APPROVED BASED ON PHOTOS SUBMITTED IN THIS DOCUMENT.

OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions have been addressed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald Signed: \_\_\_\_\_

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
402392289	FIR RESOLUTION SUBMITTED
402392301	Photo Log

Total Attach: 2 Files