

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402400471

Date Received:

05/18/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

NBL\_DJBU\_Inspections@NBLENERGY.COM

COGCC INSPECTION SUMMARY:

FIR Document Number: 697001071

Inspection Date: 04/20/2020

FIR Submit Date: 04/20/2020

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: NOBLE ENERGY INC

Company Number: 100322

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

LOCATION - Location ID: 326739

Location Name: KAMMERZELL-64N66W Number: 4SWSW County: \_\_\_\_\_

Qtrqr: SWS Sec: 4 Twp: 4N Range: 66W Meridian: 6  
W

Latitude: 40.335633 Longitude: -104.792303

FACILITY - API Number: 05-123- -00 Facility ID: 447461

Facility Name: KAMMERZELL-64N66W Number: 4SWSW

Qtrqr: SWS Sec: 4 Twp: 4N Range: 66W Meridian: 6  
W

Latitude: 40.335633 Longitude: -104.792303

CORRECTIVE ACTIONS:

1 ☒ CA# 138140

Corrective Action: Location is within a floodplain, containment berms around the tanks must be made of steel or another engineer equivalent per Rule 603.h.(2)C. Refer to the 603.h guidance document for further details.

Date: 07/21/2020

Response: CA COMPLETED

Date of Completion: 05/15/2020

Noble has fixed the berm.

Operator  
Comment:

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

2 ☒ CA# 138141

Corrective Action: Location is within a floodplain, containment berms around the tanks must be made of steel or another engineer equivalent per Rule 603.h.(2)C. Refer to the 603.h guidance document for further details.

Date: 07/21/2020

Response: CA COMPLETED

Date of Completion: 05/15/2020

Operator  
Comment: Noble has fixed the berm.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

3 ☒ CA# 138142

Corrective Action: Anchor equipment ensuring anchors are engineered so the equipment will resist flotation, collapse, lateral movement, or subsidence per Rule 603.h.(2)B. Refer to the 603.h guidance document for further details.

Date: 07/21/2020

Response: CA COMPLETED

Date of Completion: 05/15/2020

Operator  
Comment: Noble has anchored the separator.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

4 ☒ CA# 138143

Corrective Action: Anchor equipment ensuring anchors are engineered so the equipment will resist flotation, collapse, lateral movement, or subsidence per Rule 603.h.(2)B. Refer to the 603.h guidance document for further details.

Date: 07/21/2020

Response: CA COMPLETED

Date of Completion: 05/15/2020

Operator  
Comment: Noble has anchored the separator.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tesla Dougherty

Signed: \_\_\_\_\_

Title: EHS Specialist

Date: 5/18/2020 8:37:12 AM

## ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402400471	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files