

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402392320

Date Received:
05/07/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672

Name of Operator: TIMBER CREEK OPERATING LLC

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Santistevan, Vince</u>	<u>719-845-2102/719-680-9705</u>	<u>vincasantistevan@tcenergyllc.com</u>
<u>Fitzgerald, Edie</u>	<u>719-859-1394</u>	<u>ediefitzgerald@tcenergyllc.com</u>
<u>Mack, Ronald</u>		<u>ronaldmack@tcenergyllc.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 695102767

Inspection Date: 04/30/2020

FIR Submit Date: 05/01/2020

FIR Status: _____

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC

Company Number: 10672

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

LOCATION - Location ID: 309441

Location Name: NEW ELK-633S68W Number: 25SENW County: LAS ANIMAS

Qtrqtr: SENW Sec: 25 Twp: 33S Range: 68W Meridian: 6

Latitude: 37.144997 Longitude: -104.948571

FACILITY - API Number: 05-071- -00 Facility ID: 295030

Facility Name: NEW ELK Number: 25-06

Qtrqtr: SENW Sec: 25 Twp: 33S Range: 68W Meridian: 6

Latitude: 37.144997 Longitude: -104.948571

CORRECTIVE ACTIONS:

1 ☒ CA# 138573

Corrective Action: Conduct maintenance on equipment, cleanup stained material and review self inspection processes. 5-7-20.

Date: 05/07/2020

Response: CA COMPLETED

Date of Completion: 05/06/2020

Maintenance was conducted to stop the leak on the liquid ring compressor. The impacted soil around the liquid

Operator Comment: ring was removed from location. See attached photo log for details.

COGCC Decision: Approved via an AMI

COGCC Representative: APPROVED BASED ON PHOTOS SUBMITTED BY OPERATOR.

2 ☒ CA# 138574

Corrective Action: Conduct maintenance on equipment, cleanup stained material and review self inspection processes.

Date: 05/07/2020

Response: CA COMPLETED

Date of Completion: 05/06/2020

Operator Comment: Maintenance was conducted to stop the leak on the engine skid. The impacted soil was cleaned up and removed from location. See attached photo log for details.

COGCC Decision: Approved via an AMI

COGCC Representative: APPROVED BASED ON PHOTOS SUBMITTED BY OPERATOR.

3 ☒ CA# 138575

Corrective Action: Comply with general provisions of the oil and gas act for wildlife protection. PRIME MOVER ENGINE SKID IS FULL OF FLUID AND ABOUT TO RUN OVER 24 HOURS TO CORRECT 5-7-20 FOR COMPRESSOR SKID.

Date: 05/07/2020

Response: CA COMPLETED

Date of Completion: 05/01/2020

Operator Comment: The fluid accumulation in the containment below the PC engine was removed. See attached photo log for details.

COGCC Decision: Approved via an AMI

COGCC Representative: APPROVED BASED ON PHOTOS SUBMITTED BY OPERATOR.

OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions have been addressed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed: _____

Title: SR. Environmental Tech.

Date: 5/7/2020 10:48:09 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402392320	FIR RESOLUTION SUBMITTED
402392344	Photo Log

Total Attach: 2 Files